

HOW TO COMPLETE THIS REPORT

- Before the tenancy begins, the lessor or the property manager should inspect the residential premises and record the condition of the premises by indicating whether the particular room item is clean, undamaged and working by placing "Y" (YES) or "N" (NO) in the appropriate column. Where necessary, comments should be included in the report.
- Two copies of the report, which has been filled out and signed by the lessor or the property manager, must be given to the tenant within 7 days of the tenant moving into the premises.
- As soon as possible after the tenant receives the property condition report, the tenant should inspect the residential premises and complete the tenant section on both copies of the report. The tenant indicates agreement or disagreement with the condition indicated by the lessor or the property manager by placing "Y" (YES) or "N" (NO) in the appropriate column and by making any appropriate comments on the form.
- The tenant must return one copy of the completed property condition report to the lessor or the property manager within 7 days after receiving it. The tenant should keep the second copy of the property condition report.
- If photographs or video recordings are taken at the time the property inspection is carried out, it is recommended that all photographs or video recordings are signed and dated by all parties. NOTE: Photographs and/or video recordings are not a substitute for accurate written descriptions of the condition of the property.
- As soon as practicable, and in any event within 14 days after the termination of the tenancy agreement, the lessor or the property manager should complete a property condition report, indicating the condition of the premises at the end of the tenancy. This should be done in the presence of the tenant, unless the tenant has been given a reasonable opportunity to be present and has not attended the inspection.

IMPORTANT NOTES ABOUT THIS PROPERTY CONDITION REPORT

- This property condition report is an important record of the condition of the residential premises when the tenancy begins. It may be used as evidence of the state of repair or general condition of the premises at the commencement of the tenancy if there is a dispute, particularly about the return of the security bond money and any damage to the premises. It is important to complete the property condition report accurately.
- A property condition report must be filled out whether or not a security bond is paid.
- At the end of the tenancy the premises must be inspected and the condition of the premises at that time will be compared to that stated in the original property condition report.
- A tenant is not responsible for fair wear and tear to the premises. Fair wear and tear is a general term for anything that occurs through ordinary use such as the carpet becoming worn in frequently used areas. Wilful and intentional damage, or damage caused by negligence, is not fair wear and tear.
- If you do not have enough space on the report attach a separate sheet. All attachments should be signed and dated by all of the parties to the residential tenancy agreement.
- Information about the rights and responsibilities of lessors and tenants may be obtained by contacting the Department of Mines, Industry Regulation and Safety on 1300 304 054 or visiting www.dmirs.wa.gov.au/consumer-protection.

FURTHER INFORMATION

For further information about tenancy rights, refer to the *Residential Tenancies Act 1987* or contact the Department of Mines, Industry Regulation and Safety on 1300 304 054 or www.dmirs.wa.gov.au/consumer-protection.
For Translating and Interpreting Services please telephone TIS on 13 14 50 and ask to speak to the Department of Mines, Industry Regulation and Safety (1300 304 054) for assistance.



Address of premises

25 Warrida Street, Baynton WA 6714



Tenant's name(s)

The Housing Authority

Lease Start Date:

20/03/25

Inspection Date:

17/03/25



YES



NO

CONDITION CODES

SAMPLE CONDITION REPORT

Bedroom 2

Walls	Y	Y	Y	Y
Blinds / Curtains	N	Y	N	Y
Door / Doorway frame	Y	N	Y	Y
Tv Aerial port	Y	Y	Y	N
Floors Coverings	N	Y	Y	Y

Inspector Signature

Date

21/03/25

Tenant

Date

27/03/25

Agent Disclaimer.

This tenancy inspection report is a visual one carried out by Realmark Karratha to assess the manner in which the tenant is maintaining your property. As your property manager, our role is to manage the tenancy; We are not qualified to assess the structural aspects of areas including but not limited to staircases, decking and balconies or to ensure that plumbing, electrical or gas mixtures of fittings, glass windows, doors and balustrades, smoke alarms, asbestos, swimming pool safety barriers (and associated fittings) comply and operate in accordance with applicable building/council codes and/or laws and regulations. The inspection does not include the moving of furniture, lifting of floor coverings, inspecting the interiors of roof spaces, under flooring, inside of cupboards, tenant's goods or other belongings. Realmark Karratha recommends that all landlords have regular inspections carried out by suitable qualified, licensed and insured contractors and experts in the appropriate areas when necessary. Realmark Karratha also recommends that all landlords hold adequate insurance, including landlords insurance.

Additional Comments:

(may be added landlord or tenant, or both)

Housing Authority:Property requires a clean throughout including walls, garden beds, floors. Property needs to be sprayed for Singapore ants. Present at inspection.

Furniture List

If insufficient space please attach schedule

Water Meter Location	Water Meter Reading

Work Completed

Approximate date when work was last done on residential premises

Installation of water efficiency measures	
Painting of premises (internal)	
Painting of premises (external)	
Flooring laid/replaced	
Flooring cleaned	

Smoke Alarm

The landlord must indicate whether the following smoke alarm facilities are available:

Is the property fitted with Smoke Alarms?	☒
---	----------------------------------

Smoke alarm location and additional comments:

Smoke Alarms are fitted at following locations:

VTC Link

Not available

	Clean	Undamaged	Working	Inspector Comments	Tenant Agrees	Tenant Comments
Entrance						
Entrance Photos						
Floor	Y	Y		Grey marble look tiles with dark grout, clean and in good condition Refer to image: 1 2 3 4	Y N	HA: Grout is discoloured. Floors have marks/require cleaning Refer to image: 1000 1001 1002
Walls	Y	N		Off white painted walls, 4x sticky hooks, clean and in good condition. Minor scuff marks Refer to image: 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23	Y N	HA: Walls marked throughout whole entry. 4x sticker hooks not present. Refer to image: 1003 1004 1005
Door/ Doorframe	Y	Y		Off white door with stainless steel handle with lock and door stop top right in good condition Refer to image: 24 25 26 27 28 29 30 31 32 33 34	Y N	HA: Frame has chips throughout. Front door not clean and has black mark as well as marks down the bottom sticky residue on door handle Refer to image: 1006 1007 1008 1009
Lights/ Fixtures	Y	Y	Y	2x down light working 1x single light switch 1x double light switch 1x smoke alarm with green light Refer to image: 35 36 37 38	Y N	
Ceiling	Y	Y		Painted white with 1x smoke detector in clean and good condition and green light on Refer to image: 39 40 41	Y N	

Lounge Room

Lounge Room Photos

Inspector Signature

Date

21/03/25

Tenant

Date

27/03/25

CleanUndamagedWorkingInspector Comments				Tenant Agrees	Tenant Comments
Lounge Room					
Floor	Y	N	Medium size tiles marble look with dark grout, clean and in good condition. 4 x chips and 1 small crack across corner Refer to image: 42 43 44 45 46 47 48 49 50	Y N	HA: Floors not clean. Marked throughout. Two cracks. Multiple chips. Refer to image: 1010 1011 1012 1013 1014 1015 1016 1017
Walls	Y	N	Painted white with few marks and numerous sticker hooks, 1x large hole towards kitchen along bottom of wall. 2 x plastic hook above door to hallway, scuff marks noted along sections of wall. 1x aircon Refer to image: 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76	Y N	HA: No plastic hooks , however patch marks where hooks used to be. Large paint mark on wall before passage opening. No hole in kitchen. Walls marked throughout - very noticeable Refer to image: 1018 1019 1020 1021
Door/ Doorframe	Y	N	Y1x glass sliding door to outside in good condition, tracks and glass clean and locks in working order. 1 x security screen on exterior. 1x wooden doorframe (no door) to hall way Clean and in good condition Refer to image: 77 78 79 80 81 82 83 84 85 86	Y N	HA: Frame into passage has multiple chip marks/dents Refer to image: 1022 1023 1172 1173
Powerpoints/ Fixtures	Y	Y	Y2x double power points 1x tv 1x aircon remote 2x light & fan switch Refer to image: 87 88 89 90 91 92 93	Y N	
Windows/ Screens/ Window Safety Devices	N	N	Y2x large windows with black handles & locks all in good condition. 1 x fixed 1 x sliding. Glass, tracks clean, latch secure and working. Refer to image: 94 95 96 97 98 99 100 101 102	Y N	

CleanUndamagedWorking			Inspector Comments	Tenant Agrees	Tenant Comments
Lounge Room					
Blinds/ Curtains	Y	N	Y	2x black medium Vertical blinds 1x long black vertical blind In good condition with some slats bent Refer to image: 103 104 105 106 107 108 109 110 111 112 113 114 115 116 117	Y N HA: Blinds dusty. Cords tangled up to blinds to outside rear. Multiple bends to blinds to external Refer to image: 1024 1025 1026
Lights/ Fixtures	Y	Y	N	8x down lights, 2 not working Refer to image: 118 119 120	Y N
Ceiling	Y	Y		Painted white in good clean condition with cornices secure 1x white 3 bladed ceiling fan working order Refer to image: 121 122 123	Y N
Bedroom					
Bedroom Photos					
Walk In Robe	Y	Y	N	Globe does not work, 1 x wooden shelf with rail under, clean with no damage. Brown carpet as per bedroom, 1 x light switch clean and secure. Walls clean with minor marks, skirting off white and attached. Refer to image: 124 125 126 127 128 129 130 131 132 133 134 135 136	Y N HA: Carpet has marks. Walls are marked heavily Refer to image: 1027 1028 1029 1030 1031
Floor	Y	N	Y	Brown carpet clean and intact, some wear marks in traffic areas 1x paint mark LHS of entrance Refer to image: 137 138 139	Y N HA: Carpet marked in three areas. Require a vacuum Refer to image: 1032 1033 1034 1035 1036

Clean Undamaged Working Inspector Comments

Tenant
Agrees

Tenant Comments

Bedroom

Walls	Y	N	Y	White painted walls with 6x Velcro stickers Refer to image: 140 141 142 143 144 145 146 147 148 149 150 151 152 153 154 155 156	Y N	HA: No Velcro stickers. Marked throughout including patch mark above PowerPoints. Gouges on wall with largest window and black mark Wall with 2x double power points paint coming off/marked. Wall with aircon marked throughout Refer to image: 1037 1038 1039 1040 1041 1042 1043 1044
Door/ Doorframe	Y	N	Y	Painted off white door with stainless steel pull down handles in good clean condition Paint off white door frame marking on bottom Refer to image: 157 158 159 160 161 162 163 164 165	Y N	HA: Frame has chips/marks. Door marked Refer to image: 1045 1046 1047
Powerpoints/ Fixtures	Y	Y	Y	3x double power points secure and working 1x tv aerial Refer to image: 166 167 168 169 170 171	Y N	
Windows/ Screens/ Window Safety Devices	Y	Y	Y	3 x windows. 3 x panels - 2 fixed and 1 sliding. tracks, glass and frames clean, latch secure and working Refer to image: 172 173 174 175 176 177 178 179 180 181 182	Y N	
Blinds/ Curtains	Y	N	Y	Black venetian blinds secure and working order. Minor dent in slats. Cords secure Refer to image: 183 184 185 186 187 188 189 190 191 192	Y N	HA: All blinds dusty. Thread coming out of blind Refer to image: 1048 1049 1050
Lights/ Fixtures	Y	Y	Y	4x down lights all working Refer to image: 193	Y N	

Inspector Signature



Date

21/03/25

Tenant



Date

27/03/25

CleanUndamagedWorkingInspector Comments				Tenant Agrees	Tenant Comments
Bedroom					
Ceiling	Y	Y	Painted white clean and in good condition 1x white 3 bladed ceiling fan. Cornices intact and clean	Y N	
Refer to image: 194 195 196					
Ensuite					
Ensuite Photos					
Ceiling	Y	N	Painted white in good clean condition with some discoloured marks next to light.	Y N	
Refer to image: 197 198 199					
Floor/ Tiles	Y	Y	Medium size tiles, dark blue with white grout, few Calcium stains otherwise in good condition. 1 x white drain in good condition	Y N	HA: Calcium stained near shower. Refer to image: 1051
Refer to image: 200 201 202					
Walls/ Tiles	Y	N	Off white walls clean and in good condition with some minor scuff marks on corners	Y N	HA: structural crack above shower. Possible mould on wall above shower Refer to image: 1070 1071
Refer to image: 203 204 205 206 207 208 209 210					
Door/ Doorframe	Y	N	YOff yellow wooden door with stainless steel handle Chips marks on the right hand side bottom of door frame	Y N	HA: Grout/silicone coming away from frame Refer to image: 1052
Refer to image: 211 212 213 214 215 216 217 218 219					
Powerpoints/ Fixtures	Y	Y	Y1x double power points working 1x 3 switch	Y N	
Refer to image: 220 221					
Mirror/ Cabinet	Y	Y	1x large mirror with white frame Clean and in good condition	Y N	HA: Mirror not clean water marks Refer to image: 1053
Refer to image: 222					

Inspector Signature

Date21/03/25

Tenant

Date

27/03/25

	Clean	Undamaged	Working	Inspector Comments	Tenant Agrees	Tenant Comments
Ensuite						
Taps/ Basin	Y	N	Y	White basin with stainless steel taps few marks but no leaks Otherwise in good condition. Drain slightly tarnished but free from build up Refer to image: 223 224 225 226 227 228	Y N	HA: Taps have multiple calcium marks and what appears to be rust. Not clean. Drains very tarnished Refer to image: 1054 1055 1056 1057 1058
Cupboard/ Drawers	Y	Y		3x dark blue cabinets, medium draws with stainless steel handles, white laminate shelf internal clean and no damage 2x 4 dark blue cabinets with stainless steel handleswhite laminate shelf internal clean and no damage Good condition, no leaks Refer to image: 229 230 231 232 233 234 235 236 237 238 239 240	Y N	HA: Damaged to furthest cupboard. Not clean Refer to image: 1059 1060 1061 1062
Shower/ Screen/ Taps	Y	Y		3x frosted glass panels - calcium stains otherwise in good condition Medium dark blue tiles with white grout, calcium stains otherwise in good condition White wall tiles and 1 feature line tiles in clean good condition 2x stainless steel Shower head 1x large white soap dish Good condition Refer to image: 241 242 243 244 245 246 247 248 249 250 251 252 253 254 255 256 257	Y N	HA: Tiles not in good condition. Heavily stained with calcium and grout discoloured. Mould in silicone. Crack on white soap dish. Showers have build up of calcium, Refer to image: 1063 1064 1065 1066 1067 1068 1069
Toilet/ Cistern/ Seat	N	Y		White plastic lid clean and in good condition. Some discolouration in bowl from water. Minor tarnishing on flush button Refer to image: 258 259 260 261 262	Y N	HA: Whole toilet bowl discoloured. Toilet lid not secure. Refer to image: 1072
Toilet Roll Holder	Y	Y		1x stainless steel roll holder secure Refer to image: 263	Y N	

Inspector Signature



Date

21/03/25

Tenant



Date

27/03/25

	Clean	Undamaged	Working	Inspector Comments	Tenant Agrees	Tenant Comments
Ensuite						
Towel Rails	Y	Y		1x large double towel rail secure Refer to image: 264	Y N	
Windows/ Screens/ Window Safety Devices	Y	Y		1x large window with 2 frosted glass panels with black handle and lock. Tracks and glass clean and no cracks Refer to image: 265	Y N	HA: Threading Coming away Refer to image: 1073
Blinds/ Curtains	Y	Y		1x black vertical blinds clean and in good condition Refer to image: 266 267 268	Y N	
Lights/ Fixtures	Y	Y	N	1x round light- not working Refer to image: 269	Y N	
Exhaust Fan/ Vents	Y	Y	Y	1x square exhaust in good condition Refer to image: 270	Y N	
Kitchen						
Kitchen Photos						
Floor/ Tiles	Y	Y		Medium marble tiles with dark grout clean and in good condition Refer to image: 271 272 273 274	Y N	HA: Floors marked and dirty. Multiple cracked tiles Refer to image: 1074 1075 1076 1077 1078
Walls/ Tiles	Y	N		Painted white with a few marks otherwise in good condition. skirting attached clean and secure Refer to image: 275 276 277 278 279 280 281 282 283 284 285 286 287 288 289	Y N	HA: Screw above pantry. Walls marked throughout. Tiles dusty and build up with grime. Silicone Coming away Refer to image: 1079 1080 1081 1082 1083

Inspector Signature



Date

21/03/25

Tenant



Date

27/03/25

Clean	Undamaged	Working	Inspector Comments	Tenant Agrees	Tenant Comments
Kitchen					
Door/ Doorframe	Y	N	Y	Off white wooden door with stainless steel handle, chips to door frame and near handle otherwise in good condition Refer to image: 290 291 292 293 294 295 296 297 298 299 300 301 302	Y N
Powerpoints/ Fixtures	Y	Y	Y	1x double light switch 1x single power point 2x double power point 1x port 1x water switch Refer to image: 303 304 305 306 307 308	Y N
Cupboards	Y	N	Y	Off white wooden door with 2x plastic hooks to back of door and 4x large shelving and stainless steel handles. 1 x door stop on front of door. Wooden doors with silver handles, some have minor marks on through wear. White laminate shelf internally, clean and no damage Refer to image: 309 310 311 312 313 314 315 316 317 318 319 320 321 322 323 324 325 326 327 328 329 330 331 332 333 334 335 336 337 338 339 340 341 342 343 344 345 346 347 348 349 350	Y N HA: Cutlery tray broken. Wipe marks on cupboards Refer to image: 1084 1085
Benchtops/ Tiling	Y	N	Y	White marble look laminate bench top clean and in good condition. 1 x faint line/mark in front of sink on edge. Refer to image: 351 352 353 354 355 356 357 358 359 360 361 362 363 364 365 366	Y N HA: Stained in areas. Cut marks above drawers. Cut mark near hot plate Refer to image: 1086 1087 1088 1089
Sink/ Taps	Y	Y	Y	Stainless steel double sink in good condition with 2 plugs. 1 x stainless steel mixer tap with no leaks, clean Refer to image: 367 368 369 370 371 372	Y N

	Clean	Undamaged	Working	Inspector Comments	Tenant Agrees	Tenant Comments
Kitchen						
Dishwasher	Y	N		Silver Westinghouse dishwashing, 2x shelving & 1x cutlery holder in good condition Refer to image: 373 374 375 376 377 378 379 380 381 382 383 384 385 386 387	Y N	HA: Plastic cover coming off dishwasher. Damaged on side of dishwasher Refer to image: 1090
Stovetop/ Griller	Y	N	Y	Black glass stovetop with marks in good condition, some wear marks on elements. all working Refer to image: 388 389 390 391 392 393 394	Y N	
Oven	Y	Y	Y	Stainless steel oven in good condition, clean internal and glass on door. 3 x dials all clean and working. Refer to image: 395 396 397 398 399 400 401	Y N	HA: Not clean Refer to image: 1091 1092
Exhaust Fan/ Rangehood	Y	Y	N	Rangehood secure and clean, working. Filters are all clean and dials working Refer to image: 402 403 404 405	Y N	
Windows/ Screens/ Window Safety Devices	Y	Y	Y	2x long windows 2 panels with black handle & lock in good condition, clean Refer to image: 406 407 408 409	Y N	
Blinds/ Curtains	Y	N		2x black vertical blinds in good condition, secure and clean, working Refer to image: 410 411 412 413 414 415 416 417 418 419	Y N	HA: Multiple bends in both sets of blinds Refer to image: 1093 1094
Lights/ Fixtures	Y	Y	Y	2x down lights with marks around otherwise in good condition, 1 x dome light all working Refer to image: 420	Y N	

Inspector Signature



Date

21/03/25

Tenant



Date

27/03/25

Clean	Undamaged	Working	Inspector Comments	Tenant Agrees	Tenant Comments
Kitchen					
Ceiling	Y	N	Painted white with 1x large water mark from light to main wall otherwise good condition. Cornices secure Refer to image: 421 422 423	Y N	
Family room					
Family room Photos					
Floor	Y	N	Brown carpet clean and in good condition with some lighter marks Refer to image: 424 425 426	Y N	
Walls	Y	N	Painted grey, few marks & 1x aircon. white skirting secure and clean. plastic hook above window, minor chips Refer to image: 427 428 429 430 431 432 433 434 435 436 437 438 439	Y N	HA: No hook. Paint chip mark in corner. Cobwebs present. 3x chips above light switch Refer to image: 1095 1096 1098
Door/ Doorframe	Y	N	1x glossy off white wooden door with stainless steel handle in good condition, minor marks on front of doors. White laminate shelves internal Refer to image: 440 441 442 443 444 445 446 447 448 449	Y N	HA: Marks on back of doors Refer to image: 1099 1100 1101
Powerpoints/ Fixtures	Y	Y	1x aircon remote 1x double switch 1x tv 1x light switch Refer to image: 450 451 452 453 454	Y N	HA: Switch missing control knot and has crack Refer to image: 1097
Windows/ Screens/ Window Safety Devices	Y	Y	2x windows with black handle & locks in good condition. Glass, tracks and latch all secure and clean Refer to image: 455 456 457 458 459 460 461 462 463	Y N	

	Clean	Undamaged	Working	Inspector Comments	Tenant Agrees	Tenant Comments
Family room						
Blinds/ Curtains	Y	N		2x black vertical blinds in good condition, clean and secure Refer to image: 464 465 466 467 468 469	Y N	HA: 1x small bend to blind largest ones. 1x dent to small blinds dust Refer to image: 1102 1103
Lights/ Fixtures	Y	Y	N	4x down lights- 2 not working Refer to image: 470	Y N	
Ceiling	Y	Y		Painted white clean and in good condition. White cornice attached and clean Refer to image: 471 472 473 474	Y N	
Passage						
Passage Photos						
Floor	Y	Y		Medium grey marble like tiles, clean and in good condition Refer to image: 475 476 477 478	Y N	
Walls	Y	Y		Painted white with a few scuff marks otherwise good condition. Skirting clean and attached Refer to image: 479 480 481 482 483 484 485 486 487 488 489 490 491 492 493 494 495 496 497	Y N	HA: Skirtings marked throughout. Multiple black marks to skirtings skirtings not clean. Dent in wall. Walls marked throughout whole passage. 1x patch mark Refer to image: 1108 1109 1110 1111 1112 1113 1116
Door/ Doorframe	Y	N		1x linen cupboard off white with 4x shelves with stainless steel handle clean and in good condition Refer to image: 498 499 500 501 502 503 504 505 506 507	Y N	HA: Frame has multiple chip marks Refer to image: 1114
Lights/ Fixtures	Y	Y	N	2x downlights, 1 does not work Refer to image: 508 509 510	Y N	

Inspector Signature



Date

21/03/25

Tenant



Date

27/03/25

	Clean	Undamaged	Working	Inspector Comments	Tenant Agrees	Tenant Comments
Passage						
Ceiling	Y	Y		Painted white clean and in good condition with white cornices attached Refer to image: 511 512 513	Y N	HA: 1x small chip mark Refer to image: 1115
Toilet						
Toilet Photos						
Floor/ Tiles	Y	Y		Medium marble tiles with dark grout clean and in good condition. 1 white plastic drain clean Refer to image: 514 515 516	Y N	
Walls/ Tiles	Y	Y		White walls few marks otherwise clean and in good condition Refer to image: 517 518 519 520 521 522	Y N	HA: 2x patch marks on wall. Walls marked throughout Refer to image: 1117 1118
Door/ Doorframe	Y	N	Y	Off white wooden door with stainless steel handle in handle coming away a little otherwise good condition Refer to image: 523 524 525 526 527 528 529	Y N	HA: Chips on doorframe as shown in your photo
Powerpoints/ Fixtures	Y	Y	Y	1x light switch clean and secure Refer to image: 530	Y N	
Toilet/ Cistern/ Seat	Y	N	Y	White plastic lid with 1x crack, no leaks Otherwise in good condition Refer to image: 531 532 533 534 535 536 537	Y N	HA: Toilet cracked. Bowl stained Refer to image: 1119 1120
Toilet Roll Holder	Y	Y		1x stainless steel roll holder, secure Refer to image: 538	Y N	

Inspector Signature



Date

21/03/25

Tenant



Date

27/03/25

Clean	Undamaged	Working	Inspector Comments	Tenant Agrees	Tenant Comments
Toilet					
Exhaust Fan/ Vent	Y	N	Y	1x square exhaust in good condition, working Refer to image: 539 540 541 542 543 544	Y N
Bedroom 2					
Bedroom 2 Photos					
Cupboard	Y	N	N	2x large mirror sliding doors 1x stainless steel rod 1x wooden shelf Few marks otherwise in good condition Refer to image: 545 546 547 548 549 550 551 552	Y N HA: Unable to open cupboard at all. Refer to image: 1121
Floor	Y	Y		Brown carpet with 1x mark otherwise good condition Refer to image: 553 554 555	Y N
Walls	Y	N		Painted white few marks otherwise clean and in good condition Refer to image: 556 557 558 559 560 561 562 563 564 565 566 567 568 569 570 571 572 573 574 575	Y N HA: Wall paint chip Refer to image: 1124
Door/ Doorframe	Y	N	Y	Off white wooden door with stainless steel handle in good condition Refer to image: 576 577 578 579 580 581 582 583 584	Y N HA: Door has mark on front of door as well as back Refer to image: 1122 1123
Powerpoints/ Fixtures	Y	Y	Y	1x light switch 1x tv 2x double power point 1x aircon remote Refer to image: 585 586 587 588 589 590	Y N

	Clean	Undamaged	Working	Inspector Comments	Tenant Agrees	Tenant Comments
Bedroom 2						
Windows/ Screens/ Window Safety Devices	Y	N	Y	Windows clean and secure with no marks or cracks in glass or frames. tracks clean and latch secure Refer to image: 591 592 593 594	Y N	
Blinds/ Curtains	Y	N	Y	1x black vertical blinds in good working condition, clean and secure Refer to image: 595 596 597 598	Y N	HA: 1x bend I'm blind as shown in your photos
Lights/ Fixtures	Y	Y	N	1x round light attached to 3 white bladed ceiling fan - working Refer to image: 599	Y N	
Ceiling	Y	Y		Painted white with black mark otherwise in good condition. white cornices attached Refer to image: 600 601 602	Y N	HA: Black mark Refer to image: 1125
Bedroom 3						
Bedroom 3 Photos						
Cupboard	Y	Y	Y	2x large mirror sliding doors 1x stainless steel rod 1x wooden shelf Few marks otherwise in good condition Refer to image: 603 604 605 606 607 608 609 610 611	Y N	
Floor	Y	N		Dark carpet, few marks clean and in good condition Refer to image: 612 613 614 615 616 617	Y N	

	Clean	Undamaged	Working	Inspector Comments	Tenant Agrees	Tenant Comments
Bedroom 3						
Walls	Y	N		White walls, few marks and in good condition, skirting secured to walls Refer to image: 618 619 620 621 622 623 624 625 626 627 628 629 630 631 632 633 634 635 636 637 638 639 640 641 642 643 644 645 646	Y N	HA: Walls marked throughout. Hairline crack in corner of window Refer to image: 1126
Door/ Doorframe	Y	N		Off white wooden door with stainless steel handle Refer to image: 647 648 649 650 651 652 653 654 655 656 657 658 659	Y N	HA: Paint coming off above door handle. Blue mark on front of door Refer to image: 1127 1128
Powerpoints/ Fixtures	Y	Y	N	1x light/fan switch 1x aircon remote holder (no remote) 2x double power point 1x tv Refer to image: 660 661 662 663 664	Y N	
Windows/ Screens/ Window Safety Devices	Y	Y	Y	1x large window with black handle and lock in good condition. No flyscreen Refer to image: 665 666 667 668	Y N	
Blinds/ Curtains	Y	Y	Y	Black vertical blinds in good condition, clean and secure Refer to image: 669 670 671	Y N	HA: 1x bend as shown in your photos
Lights/ Fixtures	Y	Y	Y	1x round light attached to white 3 bladed ceiling fan - working Refer to image: 672	Y N	
Ceiling	Y	Y		Painted white in good condition with white cornices attached Refer to image: 673 674	Y N	

Inspector Signature



Date

21/03/25

Tenant



Date

27/03/25

	Clean	Undamaged	Working	Inspector Comments	Tenant Agrees	Tenant Comments
Bedroom 4						
Bedroom 4 Photos						
Cupboard	Y	N	Y	2x large mirror sliding doors 1x stainless steel rod 1x wooden shelf Few marks otherwise in good condition Refer to image: 675 676 677 678 679 680 681 682 683 684 685	Y N	HA: Marked throughout on walls Refer to image: 1129
Floor	Y	Y	Y	Brown carpet in good condition Refer to image: 686 687 688 689 690	Y N	HA: Stain as shown in your photos
Walls	Y	Y		Painted white in clean and in good condition, skirting attached Refer to image: 691 692 693 694 695 696 697 698 699 700 701 702 703 704 705 706 707 708 709 710 711 712 713	Y N	HA: Marked throughout, skirting have marks Refer to image: 1130 1131 1132
Door/ Doorframe	Y	Y	Y	Off white wooden door frame with stainless steel handle good condition Refer to image: 714 715 716 717 718 719 720 721 722 723 724	Y N	HA: Handle loose. Door has scratch mark on back of door as well as frame Refer to image: 1133
Powerpoints/ Fixtures	Y	Y	Y	1x aircon remote holder (no remote) 1x light switch 2x double power points 1x tv Refer to image: 725 726 727 728 729 730	Y N	
Windows/ Screens/ Window Safety Devices	Y	Y	Y	2x windows with black handle and lock in good condition. No flyscreen to big window Refer to image: 731 732 733 734 735 736	Y N	

Inspector Signature

Date21/03/25

Tenant

Date

27/03/25

	Clean	Undamaged	Working	Inspector Comments	Tenant Agrees	Tenant Comments
Bedroom 4						
Blinds/ Curtains	Y	N	Y	2x black vertical blinds in good condition Refer to image: 737 738 739 740 741	Y N	HA: Blinds damaged as shown in your photos
Lights/ Fixtures	Y	Y	Y	1x round light attached to white 3 bladed ceiling fan - working Refer to image: 742	Y N	HA: Light not working Refer to image: 1134
Ceiling	Y	Y		Painted white in good condition Refer to image: 743 744	Y N	
Bathroom						
Bathroom Photos						
Ceiling	Y	Y		Painted white in good condition with white cornices Refer to image: 745 746	Y N	
Floor/ Tiles	Y	Y		Medium dark tiles with white grout, few calcium stains otherwise in good condition Refer to image: 747 748 749 750	Y N	HA: Grout discoloured and not white.
Walls/ Tiles	Y	Y		White walls few marks otherwise in good condition Refer to image: 751 752 753 754 755 756 757 758 759 760 761 762 763	Y N	HA: Walls marked and not clean Refer to image: 1135 1136 1137
Door/ Doorframe	Y	N	Y	Off white wooden door frame with few chips and marks and stainless steel handle otherwise in good condition Refer to image: 764 765 766 767 768 769 770 771 772 773	Y N	HA: White marks on door . Not clean. Large gouge at bottom of door Refer to image: 1138 1139

Inspector Signature



Date

21/03/25

Tenant



Date

27/03/25

	Clean	Undamaged	Working	Inspector Comments	Tenant Agrees	Tenant Comments
Bathroom						
Powerpoints/ Fixtures	Y	Y	Y	1x double switch light and exhaust 1x double power point Refer to image: 774 775	Y N	
Mirror/ Cabinet	Y	Y		1x large mirror in good condition Refer to image: 776	Y N	
Taps/ Basin	Y	Y	Y	White basin with stainless steel tap, no leaks noted Refer to image: 777 778 779 780	Y N	HA: Sink drain tarnished. Tap has multiple scratch marks Refer to image: 1140 1141
Cupboard/ Drawers	Y	Y	Y	Grey vanity with 3x draws and 2x draws with stainless steel handles few marks otherwise good condition Refer to image: 781 782 783 784 785 786 787 788 789 790 791 792 793 794 795	Y N	HA: Laminate strip coming away. Vanity bench has marks Refer to image: 1142 1143 1144
Bath	Y	N	Y	1x large white bath with stainless steel soap holder and tap White tiles around in good condition Refer to image: 796 797 798 799 800 801 802 803 804 805	Y N	HA: Bath tiles are discoloured. Bath is dirty and has multiple scratches. Tiles stained Refer to image: 1145 1146 1147 1148
Shower/ Screen/ Taps	Y	Y	Y	2x frosted glass panels - 1x door Black medium tiles with calcium stains Stainless steel shower head with calcium & rust stains White wall tiles with 1x dark decorative tiles up wall 1x large white soap dish Refer to image: 806 807 808 809 810 811 812 813 814 815 816 817 818 819	Y N	HA: Mould on silicone. White tiles stained Refer to image: 1149 1150
Towel Rails	Y	Y	Y	1x large double stainless steel rail Refer to image: 820	Y N	

Inspector Signature



Date

21/03/25

Tenant



Date

27/03/25

	Clean	Undamaged	Working	Inspector Comments	Tenant Agrees	Tenant Comments
Bathroom						
Windows/ Screens/ Window Safety Devices	Y	Y	Y	2x frosted window 2 panels with black handle and lock in good condition Refer to image: 821 822 823 824	Y N	
Blinds/ Curtains	Y	N	Y	Black vertical blinds good condition Refer to image: 825 826 827 828	Y N	HA: Damaged to top of blind Refer to image: 1151
Lights/ Fixtures	Y	Y	Y	1x round light with cover in good condition Refer to image: 829	Y N	
Exhaust Fan/ Vents	Y	Y	Y	1 square exhaust fan, clean secure and no damage working Refer to image: 830	Y N	
Laundry						
Laundry Photos						
Cupboards	N	N	Y	1x large cabinet with 4x white shelf, dark brown doors and stainless steel handles in good condition 3x doors dark brown underneath sink with stainless steel handle - 1x off and under sink) Refer to image: 831 832 833 834 835 836 837 838 839 840 841 842 843 844 845 846 847 848 849 850	Y N	
Floor/ Tiles	Y	Y		Medium marble like tiles with dark grout in good condition Refer to image: 851 852 853	Y N	
Walls/ Tiles	Y	N		White walls in good condition Refer to image: 854 855 856 857 858 859 860 861 862 863 864 865 866 867 868 869	Y N	HA: Marked Refer to image: 1104 1105

Inspector Signature



Date

21/03/25

Tenant



Date

27/03/25

	Clean	Undamaged	Working	Inspector Comments	Tenant Agrees	Tenant Comments
Laundry						
Washing Machine/ Taps	Y	Y		Stainless steel taps Refer to image: 870	Y N	
Washing Tub	Y	Y		Large deep stainless steel sink with taps in good condition Refer to image: 871 872 873 874 875	Y N	
Door/ Doorframe	Y	N	Y	Off white wooden door with 1x white plastic hook on back otherwise in good condition Refer to image: 876 877 878 879 880 881 882 883 884 885 886 887 888 889 890 891 892 893 894 895 896 897 898	Y N	HA: Chip on front of door. Refer to image: 1106
Powerpoints/ Fixtures	Y	Y	Y	1x double power point 1x double switch Refer to image: 899	Y N	
Blinds/ Curtains	Y	N	Y	1x black vertical blinds in good Condition Refer to image: 900 901 902 903 904 905 906 907	Y N	HA: Bends in blinds Refer to image: 1107
Lights/ Fixtures	Y	Y	Y	1x round light with cover in good condition Refer to image: 908 909	Y N	
Ceiling	Y	Y		Painted white clean and in good condition Refer to image: 910 911	Y N	HA: Some marks
Exterior						
Exterior Photos						

	Clean	Undamaged	Working	Inspector Comments	Tenant Agrees	Tenant Comments
Exterior						
Letterbox	Y	Y	Y	Free standing grey letterbox with black 25 numbers Refer to image: 912 913 914	Y N	
Gate/ Fence	Y	N		Grey colourbond fencing, few mark without Locks on gates in good condition Refer to image: 915 916 917 918 919 920 921 922 923 924 925 926 927 928 929 930	Y N	HA: Damaged to fencing Refer to image: 1153 1154 1155
Driveway	Y	Y		2 x bins, some marks Concrete driveway clean and free from damage. Some minor marks on right hand side at garage Refer to image: 931 932 933 934 935 936 937 938 939	Y N	HA: Concrete heavily stained red. Green bin full. And car battery present. Refer to image: 1152
Footpaths	Y	Y		Grey concrete dirt otherwise in good condition Refer to image: 940 941 942 943 944 945 946 947 948 949 950	Y N	HA: Concrete stained from dirt. Refer to image: 1156
Front Lawn	Y	N		Generally green but patchy in areas and some areas that are dry. Refer to image: 951 952	Y N	HA: Dying in area. Heavy leaf debris everywhere Refer to image: 1174 1175
Back Lawn	Y	N		Back lawn is patchy with minimal green patches, very dry and long. Refer to image: 953 954 955	Y N	HA: Lawn is dead. Rocks, rubbish leaves present as well as dog bone. Garden beds not in good condition rubbish present wiring Refer to image: 1157 1158 1159 1160 1161 1162 1163 1164 1165 1176 1177
Garden Lights	Y	N		external power points and lights secured Refer to image: 956 957 958 959 960 961 962 963	Y N	

Inspector Signature



Date

21/03/25

Tenant



Date

27/03/25

	Clean	Undamaged	Working	Inspector Comments	Tenant Agrees	Tenant Comments
Exterior						
External Awnings	N	Y		Secured and clean, dirt over the concrete in far corner. Refer to image: 964 965 966 967 968 969 970 971	Y N	HA: Overall outside of house has marks and is dirty. Refer to image: 1168 1169 1170 1171
Front Porch/ Verandah	Y	Y		minor discolouration on concrete, secure and no damage Refer to image: 972 973 974 975	Y N	
Hosing/ Taps	Y	Y		External taps with calcium build up Refer to image: 976 977	Y N	
Garden Beds	N	Y		Plants are green, some debris in gardens. Leaf build up at edge of gardens Refer to image: 978 979 980 981 982 983 984 985 986 987	Y N	HA: Garden beds have heavy debris of leaves. Plants dead/dying. Rubbish throughout Refer to image: 1178 1179 1180 1181 1182 1183 1184 1185 1186 1187 1188
Storeroom						
Storeroom Photos						
Floor	N	Y		Items inside, floor dusty and debris Refer to image: 988	Y N	HA: Overall storeroom is in very poor condition. Refer to image: 1166 1167
Walls	N	Y		Colourbond walls, clean and secure with no damage Refer to image: 989 990 991	Y N	
Door/ Doorframe	N	N	Y	White wooden door with silver handle, in good condition. Door has some Pilbara staining along bottom section Refer to image: 992 993 994	Y N	

Inspector Signature



Date

21/03/25


Tenant



Date

27/03/25

	Clean	Undamaged	Working	Inspector Comments	Tenant Agrees	Tenant Comments
Storeroom						
Powerpoints/ Fixtures	N	Y	Y	External power point, secure but very dusty. Retic control box secure. Refer to image: 995 996 997	Y N	
Lights/ Fixtures	Y	Y	Y	1 x dome light secure and working Refer to image: 998	Y N	
Ceiling	Y	Y		Grey colour bond clean adn secure Refer to image: 999	Y N	



Entrance

17/03/2025 1:58 PM

Image 1 :Floor



Entrance

17/03/2025 1:58 PM

Image 2 :Floor



Entrance

17/03/2025 1:59 PM

Image 3 :Floor



Entrance

17/03/2025 1:59 PM

Image 4 :Floor

	Entrance 17/03/2025 1:59 PM Image 5 :Walls		Entrance 17/03/2025 2:00 PM Image 6 :Walls
	Entrance 17/03/2025 2:01 PM Image 7 :Walls		Entrance 17/03/2025 2:01 PM Image 8 :Walls

	Entrance 17/03/2025 2:01 PM Image 9 :Walls		Entrance 17/03/2025 2:01 PM Image 10 :Walls
	Entrance 17/03/2025 2:01 PM Image 11 :Walls		Entrance 17/03/2025 2:01 PM Image 12 :Walls

Inspector Signature



Date

21/03/25

Tenant



Date

27/03/25

	Entrance 17/03/2025 2:01 PM Image 13 :Walls		Entrance 17/03/2025 2:01 PM Image 14 :Walls
	Entrance 17/03/2025 2:02 PM Image 15 :Walls		Entrance 17/03/2025 2:02 PM Image 16 :Walls



Entrance

17/03/2025 2:02 PM

Image 17 :Walls



Entrance

17/03/2025 2:02 PM

Image 18 :Walls



Entrance

17/03/2025 2:03 PM

Image 19 :Walls



Entrance

17/03/2025 2:03 PM

Image 20 :Walls

	Entrance 17/03/2025 2:03 PM Image 21 :Walls		Entrance 17/03/2025 2:03 PM Image 22 :Walls
	Entrance 17/03/2025 2:04 PM Image 23 :Walls		Entrance 17/03/2025 2:04 PM Image 24 :Door/ Doorframe

Inspector Signature



Date


21/03/25

Tenant



Date

27/03/25



Entrance

17/03/2025 2:04 PM
Image 25 :Door/ Doorframe



Entrance

17/03/2025 2:04 PM
Image 26 :Door/ Doorframe



Entrance

17/03/2025 2:04 PM
Image 27 :Door/ Doorframe




Entrance

17/03/2025 2:04 PM
Image 28 :Door/ Doorframe

Inspector Signature  Date 21/03/25 Tenant 

Date 27/03/25




Entrance

17/03/2025 2:04 PM
Image 29 :Door/ Doorframe



Entrance

17/03/2025 2:04 PM
Image 30 :Door/ Doorframe




Entrance


17/03/2025 2:05 PM
Image 31 :Door/ Doorframe




Entrance

17/03/2025 2:05 PM
Image 32 :Door/ Doorframe

	Entrance 17/03/2025 2:05 PM Image 33 :Door/ Doorframe		Entrance 17/03/2025 2:05 PM Image 34 :Door/ Doorframe
	Entrance 17/03/2025 2:05 PM Image 35 :Lights/ Fixtures		Entrance 17/03/2025 2:05 PM Image 36 :Lights/ Fixtures

	Entrance 17/03/2025 2:05 PM Image 37 :Lights/ Fixtures		Entrance 17/03/2025 2:06 PM Image 38 :Lights/ Fixtures
	Entrance 17/03/2025 2:05 PM Image 39 :Ceiling		Entrance 17/03/2025 2:06 PM Image 40 :Ceiling



Entrance

17/03/2025 2:07 PM

Image 41 :Ceiling



Lounge Room

17/03/2025 3:09 PM

Image 42 :Floor



Lounge Room

17/03/2025 3:09 PM

Image 43 :Floor



Lounge Room

17/03/2025 3:09 PM

Image 44 :Floor

	Lounge Room 17/03/2025 3:09 PM Image 45 :Floor		Lounge Room 17/03/2025 3:09 PM Image 46 :Floor
	Lounge Room 17/03/2025 3:09 PM Image 47 :Floor		Lounge Room 17/03/2025 3:10 PM Image 48 :Floor

	Lounge Room 17/03/2025 3:10 PM Image 49 :Floor		Lounge Room 17/03/2025 3:10 PM Image 50 :Floor
	Lounge Room 17/03/2025 3:10 PM Image 51 :Walls		Lounge Room 17/03/2025 3:10 PM Image 52 :Walls

	Lounge Room 17/03/2025 3:10 PM Image 53 :Walls		Lounge Room 17/03/2025 3:10 PM Image 54 :Walls
	Lounge Room 17/03/2025 3:10 PM Image 55 :Walls		Lounge Room 17/03/2025 3:10 PM Image 56 :Walls



Lounge Room

17/03/2025 3:11 PM

Image 57 :Walls



Lounge Room

17/03/2025 3:11 PM

Image 58 :Walls



Lounge Room

17/03/2025 3:11 PM

Image 59 :Walls



Lounge Room


17/03/2025 3:11 PM

Image 60 :Walls

	Lounge Room 17/03/2025 3:11 PM Image 61 :Walls		Lounge Room 17/03/2025 3:11 PM Image 62 :Walls
	Lounge Room 17/03/2025 3:11 PM Image 63 :Walls		Lounge Room 17/03/2025 3:11 PM Image 64 :Walls

	Lounge Room 17/03/2025 3:11 PM Image 65 :Walls		Lounge Room 17/03/2025 3:12 PM Image 66 :Walls
	Lounge Room 17/03/2025 3:12 PM Image 67 :Walls		Lounge Room 17/03/2025 3:12 PM Image 68 :Walls

	Lounge Room 17/03/2025 3:12 PM Image 69 :Walls		Lounge Room 17/03/2025 3:12 PM Image 70 :Walls
	Lounge Room 17/03/2025 3:12 PM Image 71 :Walls		Lounge Room 17/03/2025 3:12 PM Image 72 :Walls

	Lounge Room 17/03/2025 3:13 PM Image 73 :Walls		Lounge Room 17/03/2025 3:13 PM Image 74 :Walls
	Lounge Room 17/03/2025 3:13 PM Image 75 :Walls		Lounge Room 17/03/2025 3:13 PM Image 76 :Walls

Inspector Signature



Date


21/03/25

Tenant



Date

27/03/25



Lounge Room
17/03/2025 3:14 PM
Image 77 :Door/ Doorframe




Lounge Room
17/03/2025 3:14 PM
Image 78 :Door/ Doorframe



Lounge Room
17/03/2025 3:14 PM
Image 79 :Door/ Doorframe




Lounge Room
17/03/2025 3:14 PM
Image 80 :Door/ Doorframe



Lounge Room
17/03/2025 3:14 PM
Image 81 :Door/ Doorframe




Lounge Room
17/03/2025 3:15 PM
Image 82 :Door/ Doorframe



Lounge Room
17/03/2025 3:15 PM
Image 83 :Door/ Doorframe



Lounge Room
17/03/2025 3:15 PM
Image 84 :Door/ Doorframe



Lounge Room
17/03/2025 3:15 PM
Image 85 :Door/ Doorframe



Lounge Room
17/03/2025 3:15 PM
Image 86 :Door/ Doorframe



Lounge Room
17/03/2025 3:15 PM
Image 87 :Powerpoints/ Fixtures



Lounge Room
17/03/2025 3:16 PM
Image 88 :Powerpoints/ Fixtures



Lounge Room
17/03/2025 3:16 PM
Image 89 :Powerpoints/ Fixtures



Lounge Room
17/03/2025 3:16 PM
Image 90 :Powerpoints/ Fixtures



Lounge Room
17/03/2025 3:16 PM
Image 91 :Powerpoints/ Fixtures



Lounge Room
17/03/2025 3:16 PM
Image 92 :Powerpoints/ Fixtures



Lounge Room
17/03/2025 3:16 PM
Image 93 :Powerpoints/ Fixtures



Lounge Room
17/03/2025 3:19 PM
Image 94 :Windows/ Screens/ Window Saf...



Lounge Room
17/03/2025 3:19 PM
Image 95 :Windows/ Screens/ Window Saf...



Lounge Room
17/03/2025 3:19 PM
Image 96 :Windows/ Screens/ Window Saf...



Lounge Room
17/03/2025 3:19 PM
Image 97 :Windows/ Screens/ Window Safe...




Lounge Room
17/03/2025 3:19 PM
Image 98 :Windows/ Screens/ Window Saf...



Lounge Room
17/03/2025 3:19 PM
Image 99 :Windows/ Screens/ Window Saf...



Lounge Room
17/03/2025 3:19 PM
Image 100 :Windows/ Screens/ Window Saf...



Lounge Room
17/03/2025 3:19 PM
Image 101 :Windows/ Screens/ Window Saf...



Lounge Room
17/03/2025 3:20 PM
Image 102 :Windows/ Screens/ Window Saf...




Lounge Room
17/03/2025 3:16 PM
Image 103 :Blinds/ Curtains



Lounge Room
17/03/2025 3:16 PM
Image 104 :Blinds/ Curtains


	Lounge Room 17/03/2025 3:17 PM Image 105 :Blinds/ Curtains		Lounge Room 17/03/2025 3:17 PM Image 106 :Blinds/ Curtains
	Lounge Room 17/03/2025 3:17 PM Image 107 :Blinds/ Curtains		Lounge Room 17/03/2025 3:17 PM Image 108 :Blinds/ Curtains



Lounge Room
17/03/2025 3:17 PM
Image 109 :Blinds/ Curtains



Lounge Room
17/03/2025 3:17 PM
Image 110 :Blinds/ Curtains




Lounge Room
17/03/2025 3:18 PM
Image 111 :Blinds/ Curtains



Lounge Room
17/03/2025 3:18 PM
Image 112 :Blinds/ Curtains

Inspector Signature  Date 21/03/25 Tenant 

Date 27/03/25



Lounge Room
17/03/2025 3:18 PM
Image 113 :Blinds/ Curtains



Lounge Room
17/03/2025 3:18 PM
Image 114 :Blinds/ Curtains




Lounge Room
17/03/2025 3:18 PM
Image 115 :Blinds/ Curtains



Lounge Room
17/03/2025 3:18 PM
Image 116 :Blinds/ Curtains

	Lounge Room 17/03/2025 3:18 PM Image 117 :Blinds/ Curtains		Lounge Room 17/03/2025 3:20 PM Image 118 :Lights/ Fixtures
	Lounge Room 17/03/2025 3:20 PM Image 119 :Lights/ Fixtures		Lounge Room 17/03/2025 3:20 PM Image 120 :Lights/ Fixtures


	Lounge Room 17/03/2025 3:21 PM Image 121 :Ceiling		Lounge Room 17/03/2025 3:21 PM Image 122 :Ceiling
	Lounge Room 17/03/2025 3:21 PM Image 123 :Ceiling		Bedroom 17/03/2025 2:18 PM Image 124 :Walk In Robe



Bedroom
17/03/2025 2:18 PM
Image 125 :Walk In Robe



Bedroom
17/03/2025 2:18 PM
Image 126 :Walk In Robe




Bedroom
17/03/2025 2:18 PM
Image 127 :Walk In Robe



Bedroom
17/03/2025 2:18 PM
Image 128 :Walk In Robe

Inspector Signature  Date 21/03/25 Tenant 

Date 27/03/25



Bedroom
17/03/2025 2:19 PM
Image 129 :Walk In Robe



Bedroom
17/03/2025 2:19 PM
Image 130 :Walk In Robe




Bedroom
17/03/2025 2:19 PM
Image 131 :Walk In Robe



Bedroom
17/03/2025 2:19 PM
Image 132 :Walk In Robe

	Bedroom 17/03/2025 2:19 PM Image 133 :Walk In Robe		Bedroom 17/03/2025 2:19 PM Image 134 :Walk In Robe
	Bedroom 17/03/2025 2:19 PM Image 135 :Walk In Robe		Bedroom 17/03/2025 2:19 PM Image 136 :Walk In Robe



Bedroom

17/03/2025 2:20 PM

Image 137 :Floor



Bedroom

17/03/2025 2:20 PM

Image 138 :Floor



Bedroom

17/03/2025 2:20 PM


Image 139 :Floor



Bedroom

17/03/2025 2:21 PM

Image 140 :Walls

	Bedroom 17/03/2025 2:21 PM Image 141 :Walls		Bedroom 17/03/2025 2:21 PM Image 142 :Walls
	Bedroom 17/03/2025 2:21 PM Image 143 :Walls		Bedroom 17/03/2025 2:21 PM Image 144 :Walls

	Bedroom 17/03/2025 2:22 PM Image 145 :Walls		Bedroom 17/03/2025 2:22 PM Image 146 :Walls
	Bedroom 17/03/2025 2:22 PM Image 147 :Walls		Bedroom 17/03/2025 2:22 PM Image 148 :Walls

Inspector Signature



Date

21/03/25


Tenant



Date

27/03/25

	Bedroom 17/03/2025 2:22 PM Image 149 :Walls		Bedroom 17/03/2025 2:22 PM Image 150 :Walls
	Bedroom 17/03/2025 2:22 PM Image 151 :Walls		Bedroom 17/03/2025 2:22 PM Image 152 :Walls



Bedroom
17/03/2025 2:22 PM
[Image 153 :Walls](#)



Bedroom
17/03/2025 2:23 PM
[Image 154 :Walls](#)




Bedroom
17/03/2025 2:23 PM
[Image 155 :Walls](#)



Bedroom
17/03/2025 2:23 PM
[Image 156 :Walls](#)

Inspector Signature  Date 21/03/25 Tenant 

Date 27/03/25



Bedroom

17/03/2025 2:23 PM

Image 157 :Door/ Doorframe



Bedroom

17/03/2025 2:23 PM

Image 158 :Door/ Doorframe



Bedroom

17/03/2025 2:24 PM

Image 159 :Door/ Doorframe



Bedroom

17/03/2025 2:24 PM

Image 160 :Door/ Doorframe

	Bedroom 17/03/2025 2:24 PM Image 161 :Door/ Doorframe		Bedroom 17/03/2025 2:24 PM Image 162 :Door/ Doorframe
	Bedroom 17/03/2025 2:24 PM Image 163 :Door/ Doorframe		Bedroom 17/03/2025 2:24 PM Image 164 :Door/ Doorframe

Inspector Signature



Date

21/03/25

Tenant



Date

27/03/25

	Bedroom 17/03/2025 2:25 PM Image 165 :Door/ Doorframe		Bedroom 17/03/2025 2:24 PM Image 166 :Powerpoints/ Fixtures
	Bedroom 17/03/2025 2:25 PM Image 167 :Powerpoints/ Fixtures		Bedroom 17/03/2025 2:25 PM Image 168 :Powerpoints/ Fixtures



Bedroom
17/03/2025 2:25 PM
Image 169 :Powerpoints/ Fixtures




Bedroom
17/03/2025 2:25 PM
Image 170 :Powerpoints/ Fixtures



Bedroom
17/03/2025 2:25 PM
Image 171 :Powerpoints/ Fixtures




Bedroom
17/03/2025 2:26 PM
Image 172 :Windows/ Screens/ Window Saf...



Bedroom
17/03/2025 2:26 PM
Image 173 :Windows/ Screens/ Window Saf...




Bedroom
17/03/2025 2:26 PM
Image 174 :Windows/ Screens/ Window Saf...



Bedroom
17/03/2025 2:26 PM
Image 175 :Windows/ Screens/ Window Saf...




Bedroom
17/03/2025 2:27 PM
Image 176 :Windows/ Screens/ Window Saf...



Bedroom
17/03/2025 2:27 PM
Image 177 :Windows/ Screens/ Window Saf...




Bedroom
17/03/2025 2:27 PM
Image 178 :Windows/ Screens/ Window Saf...



Bedroom
17/03/2025 2:27 PM
Image 179 :Windows/ Screens/ Window Saf...



Bedroom
17/03/2025 2:29 PM
Image 180 :Windows/ Screens/ Window Saf...



Bedroom

17/03/2025 2:29 PM


Image 181 :Windows/ Screens/ Window Saf...



Bedroom

17/03/2025 2:29 PM

Image 182 :Windows/ Screens/ Window Saf...



Bedroom

17/03/2025 2:26 PM

Image 183 :Blinds/ Curtains



Bedroom

17/03/2025 2:26 PM


Image 184 :Blinds/ Curtains

Inspector Signature 

Date 21/03/25

Tenant 

Date 27/03/25



Bedroom

17/03/2025 2:26 PM

Image 185 :Blinds/ Curtains



Bedroom

17/03/2025 2:26 PM

Image 186 :Blinds/ Curtains



Bedroom

17/03/2025 2:27 PM

Image 187 :Blinds/ Curtains




Bedroom

17/03/2025 2:27 PM


Image 188 :Blinds/ Curtains

	Bedroom 17/03/2025 2:27 PM Image 189 :Blinds/ Curtains		Bedroom 17/03/2025 2:29 PM Image 190 :Blinds/ Curtains
	Bedroom 17/03/2025 2:29 PM Image 191 :Blinds/ Curtains		Bedroom 17/03/2025 2:29 PM Image 192 :Blinds/ Curtains


	Bedroom 17/03/2025 2:28 PM Image 193 :Lights/ Fixtures		Bedroom 17/03/2025 2:28 PM Image 194 :Ceiling
	Bedroom 17/03/2025 2:28 PM Image 195 :Ceiling		Bedroom 17/03/2025 2:28 PM Image 196 :Ceiling



Ensuite
17/03/2025 2:30 PM
Image 197 :Ceiling




Ensuite
17/03/2025 2:30 PM
Image 198 :Ceiling



Ensuite
17/03/2025 2:30 PM
Image 199 :Ceiling



Ensuite
17/03/2025 2:30 PM
Image 200 :Floor/ Tiles



Ensuite

17/03/2025 2:30 PM

Image 201 :Floor/ Tiles



Ensuite

17/03/2025 2:32 PM

Image 202 :Floor/ Tiles



Ensuite

17/03/2025 2:32 PM


Image 203 :Walls/ Tiles



Ensuite

17/03/2025 2:32 PM


Image 204 :Walls/ Tiles



Ensuite
17/03/2025 2:32 PM
Image 205 :Walls/ Tiles



Ensuite
17/03/2025 2:32 PM
Image 206 :Walls/ Tiles




Ensuite
17/03/2025 2:33 PM
Image 207 :Walls/ Tiles



Ensuite
17/03/2025 2:33 PM
Image 208 :Walls/ Tiles

Inspector Signature  Date 21/03/25 Tenant 

Date 27/03/25



Ensuite
17/03/2025 2:33 PM
Image 209 :Walls/ Tiles



Ensuite
17/03/2025 2:33 PM
Image 210 :Walls/ Tiles



Ensuite
17/03/2025 2:33 PM
Image 211 :Door/ Doorframe



Ensuite
17/03/2025 2:33 PM
Image 212 :Door/ Doorframe



Ensuite

17/03/2025 2:33 PM

Image 213 :Door/ Doorframe



Ensuite

17/03/2025 2:33 PM

Image 214 :Door/ Doorframe



Ensuite

17/03/2025 2:33 PM


Image 215 :Door/ Doorframe



Ensuite

17/03/2025 2:34 PM

Image 216 :Door/ Doorframe



Ensuite

17/03/2025 2:34 PM

Image 217 :Door/ Doorframe



Ensuite

17/03/2025 2:34 PM

Image 218 :Door/ Doorframe



Ensuite

17/03/2025 2:34 PM

Image 219 :Door/ Doorframe



Ensuite

17/03/2025 2:35 PM

Image 220 :Powerpoints/ Fixtures

Inspector Signature 

Date 21/03/25

Tenant 

Date 27/03/25

	Ensuite 17/03/2025 2:35 PM Image 221 :Powerpoints/ Fixtures		Ensuite 17/03/2025 2:35 PM Image 222 :Mirror/ Cabinet
	Ensuite 17/03/2025 2:35 PM Image 223 :Taps/ Basin		Ensuite 17/03/2025 2:36 PM Image 224 :Taps/ Basin



Ensuite

17/03/2025 2:36 PM
Image 225 :Taps/ Basin



Ensuite

17/03/2025 2:36 PM
Image 226 :Taps/ Basin



Ensuite

17/03/2025 2:36 PM
Image 227 :Taps/ Basin




Ensuite

17/03/2025 2:36 PM
Image 228 :Taps/ Basin

Inspector Signature  Date 21/03/25 Tenant 

Date 27/03/25



Ensuite
17/03/2025 2:36 PM
Image 229 :Cupboard/ Drawers




Ensuite
17/03/2025 2:36 PM
Image 230 :Cupboard/ Drawers



Ensuite
17/03/2025 2:36 PM
Image 231 :Cupboard/ Drawers



Ensuite
17/03/2025 2:36 PM
Image 232 :Cupboard/ Drawers



Ensuite
17/03/2025 2:36 PM
Image 233 :Cupboard/ Drawers




Ensuite
17/03/2025 2:37 PM
Image 234 :Cupboard/ Drawers



Ensuite
17/03/2025 2:37 PM
Image 235 :Cupboard/ Drawers



Ensuite
17/03/2025 2:37 PM
Image 236 :Cupboard/ Drawers



Ensuite

17/03/2025 2:37 PM

Image 237 :Cupboard/ Drawers



Ensuite

17/03/2025 2:37 PM

Image 238 :Cupboard/ Drawers



Ensuite

17/03/2025 2:37 PM

Image 239 :Cupboard/ Drawers



Ensuite

17/03/2025 2:37 PM

Image 240 :Cupboard/ Drawers



Ensuite

17/03/2025 2:38 PM

Image 241 :Shower/ Screen/ Taps



Ensuite

17/03/2025 2:38 PM

Image 242 :Shower/ Screen/ Taps



Ensuite

17/03/2025 2:38 PM


Image 243 :Shower/ Screen/ Taps



Ensuite

17/03/2025 2:38 PM

Image 244 :Shower/ Screen/ Taps



Ensuite

17/03/2025 2:38 PM


Image 245 :Shower/ Screen/ Taps



Ensuite

17/03/2025 2:38 PM

Image 246 :Shower/ Screen/ Taps



Ensuite

17/03/2025 2:39 PM

Image 247 :Shower/ Screen/ Taps



Ensuite

17/03/2025 2:39 PM


Image 248 :Shower/ Screen/ Taps

Inspector Signature 

Date 21/03/25

Tenant 

Date 27/03/25



Ensuite

17/03/2025 2:39 PM

Image 249 :Shower/ Screen/ Taps



Ensuite

17/03/2025 2:39 PM

Image 250 :Shower/ Screen/ Taps



Ensuite

17/03/2025 2:39 PM


Image 251 :Shower/ Screen/ Taps



Ensuite

17/03/2025 2:39 PM

Image 252 :Shower/ Screen/ Taps



Ensuite

17/03/2025 2:39 PM

Image 253 :Shower/ Screen/ Taps



Ensuite

17/03/2025 2:39 PM

Image 254 :Shower/ Screen/ Taps



Ensuite

17/03/2025 2:39 PM


Image 255 :Shower/ Screen/ Taps



Ensuite

17/03/2025 2:39 PM

Image 256 :Shower/ Screen/ Taps



Ensuite

17/03/2025 2:39 PM

Image 257 :Shower/ Screen/ Taps



Ensuite

17/03/2025 2:39 PM

Image 258 :Toilet/ Cistern/ Seat



Ensuite

17/03/2025 2:39 PM

Image 259 :Toilet/ Cistern/ Seat



Ensuite

17/03/2025 2:40 PM

Image 260 :Toilet/ Cistern/ Seat



Ensuite
17/03/2025 2:40 PM
Image 261 :Toilet/ Cistern/ Seat



Ensuite
17/03/2025 2:40 PM
Image 262 :Toilet/ Cistern/ Seat



Ensuite
17/03/2025 2:40 PM
Image 263 :Toilet Roll Holder



Ensuite
17/03/2025 2:40 PM
Image 264 :Towel Rails



Ensuite

17/03/2025 2:40 PM
Image 265 :Windows/ Screens/ Window Sa...




Ensuite

17/03/2025 2:41 PM
Image 266 :Blinds/ Curtains



Ensuite

17/03/2025 2:41 PM
Image 267 :Blinds/ Curtains




Ensuite

17/03/2025 2:41 PM
Image 268 :Blinds/ Curtains

Inspector Signature  Date 21/03/25 Tenant 

Date 27/03/25



Ensuite

17/03/2025 2:41 PM
Image 269 :Lights/ Fixtures



Ensuite

17/03/2025 2:41 PM
Image 270 :Exhaust Fan/ Vents



Kitchen

17/03/2025 2:43 PM
Image 271 :Floor/ Tiles




Kitchen

17/03/2025 2:43 PM
Image 272 :Floor/ Tiles

Inspector Signature  Date 21/03/25 Tenant 

Date 27/03/25

	Kitchen 17/03/2025 2:44 PM Image 273 :Floor/ Tiles		Kitchen 17/03/2025 2:44 PM Image 274 :Floor/ Tiles
	Kitchen 17/03/2025 2:45 PM Image 275 :Walls/ Tiles		Kitchen 17/03/2025 2:45 PM Image 276 :Walls/ Tiles

	Kitchen 17/03/2025 2:45 PM Image 277 :Walls/ Tiles		Kitchen 17/03/2025 2:45 PM Image 278 :Walls/ Tiles
	Kitchen 17/03/2025 2:45 PM Image 279 :Walls/ Tiles		Kitchen 17/03/2025 2:45 PM Image 280 :Walls/ Tiles

Inspector Signature



Date


21/03/25

Tenant



Date

27/03/25



Kitchen
17/03/2025 2:45 PM
Image 281 :Walls/ Tiles



Kitchen
17/03/2025 2:45 PM
Image 282 :Walls/ Tiles




Kitchen
17/03/2025 2:45 PM
Image 283 :Walls/ Tiles



Kitchen
17/03/2025 2:46 PM
Image 284 :Walls/ Tiles

Inspector Signature  Date 21/03/25 Tenant 

Date 27/03/25



Kitchen
17/03/2025 2:46 PM
Image 285 :Walls/ Tiles




Kitchen
17/03/2025 2:46 PM
Image 286 :Walls/ Tiles



Kitchen
17/03/2025 2:46 PM
Image 287 :Walls/ Tiles



Kitchen
17/03/2025 2:46 PM
Image 288 :Walls/ Tiles



Kitchen
17/03/2025 3:08 PM
Image 289 :Walls/ Tiles



Kitchen
17/03/2025 2:47 PM
Image 290 :Door/ Doorframe



Kitchen
17/03/2025 2:47 PM
Image 291 :Door/ Doorframe



Kitchen
17/03/2025 2:47 PM
Image 292 :Door/ Doorframe

Inspector Signature  Date 21/03/25 Tenant 

Date 27/03/25

	Kitchen 17/03/2025 2:47 PM Image 293 :Door/ Doorframe		Kitchen 17/03/2025 2:47 PM Image 294 :Door/ Doorframe
	Kitchen 17/03/2025 2:47 PM Image 295 :Door/ Doorframe		Kitchen 17/03/2025 2:47 PM Image 296 :Door/ Doorframe

Inspector Signature



Date

21/03/25

Tenant



Date

27/03/25

	Kitchen 17/03/2025 2:47 PM Image 297 :Door/ Doorframe		Kitchen 17/03/2025 2:48 PM Image 298 :Door/ Doorframe
	Kitchen 17/03/2025 2:48 PM Image 299 :Door/ Doorframe		Kitchen 17/03/2025 2:48 PM Image 300 :Door/ Doorframe



Kitchen

17/03/2025 2:48 PM
Image 301 :Door/ Doorframe



Kitchen

17/03/2025 2:48 PM
Image 302 :Door/ Doorframe



Kitchen

17/03/2025 2:48 PM
Image 303 :Powerpoints/ Fixtures



Kitchen

17/03/2025 2:48 PM
Image 304 :Powerpoints/ Fixtures

	Kitchen 17/03/2025 2:48 PM Image 305 :Powerpoints/ Fixtures		Kitchen 17/03/2025 2:48 PM Image 306 :Powerpoints/ Fixtures
	Kitchen 17/03/2025 2:49 PM Image 307 :Powerpoints/ Fixtures		Kitchen 17/03/2025 2:49 PM Image 308 :Powerpoints/ Fixtures



Kitchen
17/03/2025 2:49 PM
Image 309 :Cupboards



Kitchen
17/03/2025 2:49 PM
Image 310 :Cupboards



Kitchen
17/03/2025 2:49 PM
Image 311 :Cupboards



Kitchen
17/03/2025 2:49 PM
Image 312 :Cupboards



Kitchen

17/03/2025 2:49 PM

Image 313 :Cupboards



Kitchen

17/03/2025 2:49 PM

Image 314 :Cupboards



Kitchen

17/03/2025 2:50 PM


Image 315 :Cupboards




Kitchen

17/03/2025 2:50 PM

Image 316 :Cupboards

	Kitchen 17/03/2025 2:50 PM Image 317 :Cupboards		Kitchen 17/03/2025 2:50 PM Image 318 :Cupboards
	Kitchen 17/03/2025 2:50 PM Image 319 :Cupboards		Kitchen 17/03/2025 2:50 PM Image 320 :Cupboards



Kitchen
17/03/2025 2:50 PM
Image 321 :Cupboards




Kitchen
17/03/2025 2:50 PM
Image 322 :Cupboards



Kitchen
17/03/2025 2:51 PM
Image 323 :Cupboards



Kitchen
17/03/2025 2:51 PM
Image 324 :Cupboards



Kitchen
17/03/2025 2:51 PM
Image 325 :Cupboards




Kitchen
17/03/2025 2:52 PM
Image 326 :Cupboards



Kitchen
17/03/2025 2:52 PM
Image 327 :Cupboards




Kitchen
17/03/2025 2:52 PM
Image 328 :Cupboards



Kitchen
17/03/2025 2:52 PM
Image 329 :Cupboards



Kitchen
17/03/2025 2:52 PM
Image 330 :Cupboards



Kitchen
17/03/2025 2:52 PM
Image 331 :Cupboards



Kitchen
17/03/2025 2:52 PM
Image 332 :Cupboards

Inspector Signature  Date 21/03/25 Tenant 


Date 27/03/25



Kitchen
17/03/2025 2:52 PM
Image 333 :Cupboards



Kitchen
17/03/2025 2:52 PM
Image 334 :Cupboards




Kitchen
17/03/2025 2:52 PM
Image 335 :Cupboards



Kitchen
17/03/2025 2:52 PM
Image 336 :Cupboards

Inspector Signature  Date 21/03/25 Tenant 


Date 27/03/25



Kitchen
17/03/2025 2:53 PM
Image 337 :Cupboards




Kitchen
17/03/2025 2:53 PM
Image 338 :Cupboards



Kitchen
17/03/2025 2:53 PM
Image 339 :Cupboards



Kitchen
17/03/2025 2:53 PM
Image 340 :Cupboards



Kitchen
17/03/2025 2:53 PM
Image 341 :Cupboards




Kitchen
17/03/2025 2:53 PM
Image 342 :Cupboards



Kitchen
17/03/2025 2:53 PM
Image 343 :Cupboards



Kitchen
17/03/2025 2:53 PM
Image 344 :Cupboards



Kitchen
17/03/2025 2:53 PM
Image 345 :Cupboards




Kitchen
17/03/2025 2:53 PM
Image 346 :Cupboards




Kitchen
17/03/2025 2:53 PM
Image 347 :Cupboards




Kitchen
17/03/2025 2:53 PM
Image 348 :Cupboards




Kitchen
17/03/2025 2:54 PM
Image 349 :Cupboards



Kitchen
17/03/2025 2:54 PM
Image 350 :Cupboards



Kitchen
17/03/2025 2:54 PM
Image 351 :Benchtops/ Tiling



Kitchen
17/03/2025 2:54 PM
Image 352 :Benchtops/ Tiling

Inspector Signature  Date 21/03/25 Tenant 

Date 27/03/25

	Kitchen 17/03/2025 2:54 PM Image 353 :Benchtops/ Tiling		Kitchen 17/03/2025 2:54 PM Image 354 :Benchtops/ Tiling
	Kitchen 17/03/2025 2:54 PM Image 355 :Benchtops/ Tiling		Kitchen 17/03/2025 2:55 PM Image 356 :Benchtops/ Tiling

Inspector Signature



Date


21/03/25

Tenant



Date

27/03/25



Kitchen
17/03/2025 2:55 PM
Image 357 :Benchtops/ Tiling



Kitchen
17/03/2025 2:55 PM
Image 358 :Benchtops/ Tiling



Kitchen
17/03/2025 2:55 PM
Image 359 :Benchtops/ Tiling




Kitchen
17/03/2025 2:55 PM
Image 360 :Benchtops/ Tiling




Kitchen

17/03/2025 2:56 PM
Image 361 :Benchtops/ Tiling



Kitchen

17/03/2025 2:56 PM
Image 362 :Benchtops/ Tiling




Kitchen

17/03/2025 2:56 PM
Image 363 :Benchtops/ Tiling



Kitchen

17/03/2025 2:56 PM
Image 364 :Benchtops/ Tiling



Kitchen
17/03/2025 2:56 PM
Image 365 :Benchtops/ Tiling



Kitchen
17/03/2025 2:56 PM
Image 366 :Benchtops/ Tiling



Kitchen
17/03/2025 2:57 PM
Image 367 :Sink/ Taps



Kitchen
17/03/2025 2:57 PM
Image 368 :Sink/ Taps

	Kitchen 17/03/2025 2:57 PM Image 369 :Sink/ Taps		Kitchen 17/03/2025 2:57 PM Image 370 :Sink/ Taps
	Kitchen 17/03/2025 2:57 PM Image 371 :Sink/ Taps		Kitchen 17/03/2025 2:58 PM Image 372 :Sink/ Taps



Kitchen
17/03/2025 2:58 PM
Image 373 :Dishwasher




Kitchen
17/03/2025 2:58 PM
Image 374 :Dishwasher



Kitchen
17/03/2025 2:58 PM
Image 375 :Dishwasher



Kitchen
17/03/2025 2:58 PM
Image 376 :Dishwasher



Kitchen
17/03/2025 2:58 PM
Image 377 :Dishwasher



Kitchen
17/03/2025 2:58 PM
Image 378 :Dishwasher



Kitchen
17/03/2025 2:58 PM
Image 379 :Dishwasher



Kitchen
17/03/2025 2:59 PM
Image 380 :Dishwasher



Kitchen
17/03/2025 2:59 PM
Image 381 :Dishwasher



Kitchen
17/03/2025 2:59 PM
Image 382 :Dishwasher



Kitchen
17/03/2025 2:59 PM
Image 383 :Dishwasher



Kitchen
17/03/2025 2:59 PM
Image 384 :Dishwasher



Kitchen
17/03/2025 2:59 PM
Image 385 :Dishwasher



Kitchen
17/03/2025 2:59 PM
Image 386 :Dishwasher



Kitchen
17/03/2025 2:59 PM
Image 387 :Dishwasher



Kitchen
17/03/2025 3:00 PM
Image 388 :Stovetop/ Griller

Inspector Signature  Date 21/03/25 Tenant 

Date 27/03/25



Kitchen

17/03/2025 3:00 PM
Image 389 :Stovetop/ Griller



Kitchen

17/03/2025 3:00 PM
Image 390 :Stovetop/ Griller



Kitchen

17/03/2025 3:00 PM
Image 391 :Stovetop/ Griller



Kitchen

17/03/2025 3:01 PM
Image 392 :Stovetop/ Griller



Kitchen

17/03/2025 3:01 PM
Image 393 :Stovetop/ Griller



Kitchen

17/03/2025 3:02 PM
Image 394 :Stovetop/ Griller



Kitchen

17/03/2025 3:03 PM
Image 395 :Oven



Kitchen

17/03/2025 3:03 PM
Image 396 :Oven



Kitchen

17/03/2025 3:03 PM

Image 397 :Oven



Kitchen

17/03/2025 3:03 PM

Image 398 :Oven



Kitchen

17/03/2025 3:03 PM

Image 399 :Oven



Kitchen

17/03/2025 3:03 PM

Image 400 :Oven



Kitchen
17/03/2025 3:03 PM
Image 401 :Oven



Kitchen
17/03/2025 3:04 PM
Image 402 :Exhaust Fan/ Rangehood



Kitchen
17/03/2025 3:04 PM
Image 403 :Exhaust Fan/ Rangehood



Kitchen
17/03/2025 3:04 PM
Image 404 :Exhaust Fan/ Rangehood



Kitchen
17/03/2025 3:04 PM
Image 405 :Exhaust Fan/ Rangehood




Kitchen
17/03/2025 3:05 PM
Image 406 :Windows/ Screens/ Window Sa...



Kitchen
17/03/2025 3:05 PM
Image 407 :Windows/ Screens/ Window Sa...



Kitchen
17/03/2025 3:06 PM
Image 408 :Windows/ Screens/ Window Sa...



Kitchen
17/03/2025 3:06 PM
Image 409 :Windows/ Screens/ Window Sa...



Kitchen
17/03/2025 3:04 PM
Image 410 :Blinds/ Curtains



Kitchen
17/03/2025 3:05 PM
Image 411 :Blinds/ Curtains



Kitchen
17/03/2025 3:05 PM
Image 412 :Blinds/ Curtains

Inspector Signature  Date 21/03/25 Tenant 

Date 27/03/25



Kitchen

17/03/2025 3:05 PM

Image 413 :Blinds/ Curtains



Kitchen

17/03/2025 3:05 PM

Image 414 :Blinds/ Curtains



Kitchen

17/03/2025 3:05 PM

Image 415 :Blinds/ Curtains




Kitchen


17/03/2025 3:05 PM

Image 416 :Blinds/ Curtains


	Kitchen 17/03/2025 3:05 PM Image 417 :Blinds/ Curtains		Kitchen 17/03/2025 3:05 PM Image 418 :Blinds/ Curtains
	Kitchen 17/03/2025 3:05 PM Image 419 :Blinds/ Curtains		Kitchen 17/03/2025 3:06 PM Image 420 :Lights/ Fixtures



Kitchen
17/03/2025 3:07 PM
Image 421 :Ceiling



Kitchen
17/03/2025 3:07 PM
Image 422 :Ceiling



Kitchen
17/03/2025 3:07 PM
Image 423 :Ceiling



Family room
17/03/2025 2:07 PM
Image 424 :Floor

	Family room 17/03/2025 2:07 PM Image 425 :Floor		Family room 17/03/2025 2:07 PM Image 426 :Floor
	Family room 17/03/2025 2:08 PM Image 427 :Walls		Family room 17/03/2025 2:08 PM Image 428 :Walls

Inspector Signature



Date


21/03/25

Tenant



Date

27/03/25



Family room

17/03/2025 2:08 PM

Image 429 :Walls



Family room

17/03/2025 2:08 PM

Image 430 :Walls



Family room

17/03/2025 2:08 PM


Image 431 :Walls




Family room

17/03/2025 2:09 PM

Image 432 :Walls


	Family room 17/03/2025 2:09 PM Image 433 :Walls		Family room 17/03/2025 2:09 PM Image 434 :Walls
	Family room 17/03/2025 2:09 PM Image 435 :Walls		Family room 17/03/2025 2:09 PM Image 436 :Walls



Family room
17/03/2025 2:09 PM
Image 437 :Walls



Family room
17/03/2025 2:09 PM
Image 438 :Walls



Family room
17/03/2025 2:10 PM
Image 439 :Walls



Family room
17/03/2025 2:12 PM
Image 440 :Door/ Doorframe

Inspector Signature  Date 21/03/25 Tenant 

Date 27/03/25

	Family room 17/03/2025 2:12 PM Image 441 :Door/ Doorframe		Family room 17/03/2025 2:12 PM Image 442 :Door/ Doorframe
	Family room 17/03/2025 2:12 PM Image 443 :Door/ Doorframe		Family room 17/03/2025 2:12 PM Image 444 :Door/ Doorframe

Inspector Signature



Date


21/03/25

Tenant



Date

27/03/25



Family room
17/03/2025 2:12 PM
Image 445 :Door/ Doorframe



Family room
17/03/2025 2:13 PM
Image 446 :Door/ Doorframe



Family room
17/03/2025 2:13 PM
Image 447 :Door/ Doorframe



Family room
17/03/2025 2:13 PM
Image 448 :Door/ Doorframe


	Family room 17/03/2025 2:13 PM Image 449 :Door/ Doorframe		Family room 17/03/2025 2:13 PM Image 450 :Powerpoints/ Fixtures
	Family room 17/03/2025 2:13 PM Image 451 :Powerpoints/ Fixtures		Family room 17/03/2025 2:14 PM Image 452 :Powerpoints/ Fixtures




Family room
17/03/2025 2:14 PM
Image 453 :Powerpoints/ Fixtures



Family room
17/03/2025 2:14 PM
Image 454 :Powerpoints/ Fixtures



Family room
17/03/2025 2:15 PM
Image 455 :Windows/ Screens/ Window Sa...



Family room
17/03/2025 2:15 PM
Image 456 :Windows/ Screens/ Window Sa...

	Family room 17/03/2025 2:15 PM Image 457 :Windows/ Screens/ Window Sa...		Family room 17/03/2025 2:15 PM Image 458 :Windows/ Screens/ Window Sa...
	Family room 17/03/2025 2:15 PM Image 459 :Windows/ Screens/ Window Sa...		Family room 17/03/2025 2:16 PM Image 460 :Windows/ Screens/ Window Sa...

Inspector Signature



Date


21/03/25

Tenant



Date

27/03/25




Family room
17/03/2025 2:16 PM
Image 461 :Windows/ Screens/ Window Saf...



Family room
17/03/2025 2:16 PM
Image 462 :Windows/ Screens/ Window Sa...




Family room
17/03/2025 2:16 PM
Image 463 :Windows/ Screens/ Window Sa...



Family room
17/03/2025 2:14 PM
Image 464 :Blinds/ Curtains

	Family room 17/03/2025 2:14 PM Image 465 :Blinds/ Curtains		Family room 17/03/2025 2:15 PM Image 466 :Blinds/ Curtains
	Family room 17/03/2025 2:15 PM Image 467 :Blinds/ Curtains		Family room 17/03/2025 2:15 PM Image 468 :Blinds/ Curtains




Family room
17/03/2025 2:15 PM
Image 469 :Blinds/ Curtains



Family room
17/03/2025 2:16 PM
Image 470 :Lights/ Fixtures



Family room
17/03/2025 2:17 PM
Image 471 :Ceiling



Family room
17/03/2025 2:17 PM
Image 472 :Ceiling



Family room

17/03/2025 2:17 PM


Image 473 :Ceiling



Family room

17/03/2025 2:17 PM


Image 474 :Ceiling



Passage

17/03/2025 3:22 PM

Image 475 :Floor





Passage

17/03/2025 3:22 PM

Image 476 :Floor

	Passage 17/03/2025 3:22 PM Image 477 :Floor		Passage 17/03/2025 3:22 PM Image 478 :Floor
	Passage 17/03/2025 3:22 PM Image 479 :Walls		Passage 17/03/2025 3:23 PM Image 480 :Walls

	Passage 17/03/2025 3:23 PM Image 481 :Walls		Passage 17/03/2025 3:23 PM Image 482 :Walls
	Passage 17/03/2025 3:23 PM Image 483 :Walls		Passage 17/03/2025 3:23 PM Image 484 :Walls

	Passage 17/03/2025 3:23 PM Image 485 :Walls		Passage 17/03/2025 3:23 PM Image 486 :Walls
	Passage 17/03/2025 3:23 PM Image 487 :Walls		Passage 17/03/2025 3:24 PM Image 488 :Walls

	Passage 17/03/2025 3:24 PM Image 489 :Walls		Passage 17/03/2025 3:24 PM Image 490 :Walls
	Passage 17/03/2025 3:24 PM Image 491 :Walls		Passage 17/03/2025 3:24 PM Image 492 :Walls

	Passage 17/03/2025 3:24 PM Image 493 :Walls		Passage 17/03/2025 3:24 PM Image 494 :Walls
	Passage 17/03/2025 3:24 PM Image 495 :Walls		Passage 17/03/2025 3:24 PM Image 496 :Walls

Inspector Signature



Date

21/03/25


Tenant



Date

27/03/25

	Passage 17/03/2025 3:25 PM Image 497 :Walls		Passage 17/03/2025 3:25 PM Image 498 :Door/ Doorframe
	Passage 17/03/2025 3:25 PM Image 499 :Door/ Doorframe		Passage 17/03/2025 3:25 PM Image 500 :Door/ Doorframe



Passage
17/03/2025 3:25 PM
Image 501 :Door/ Doorframe



Passage
17/03/2025 3:25 PM
Image 502 :Door/ Doorframe



Passage
17/03/2025 3:26 PM
Image 503 :Door/ Doorframe




Passage
17/03/2025 3:26 PM
Image 504 :Door/ Doorframe

Inspector Signature  Date 21/03/25 Tenant 

Date 27/03/25

	Passage 17/03/2025 3:26 PM Image 505 :Door/ Doorframe		Passage 17/03/2025 3:26 PM Image 506 :Door/ Doorframe
	Passage 17/03/2025 3:26 PM Image 507 :Door/ Doorframe		Passage 17/03/2025 3:26 PM Image 508 :Lights/ Fixtures

	Passage 17/03/2025 3:26 PM Image 509 :Lights/ Fixtures		Passage 17/03/2025 3:28 PM Image 510 :Lights/ Fixtures
	Passage 17/03/2025 3:27 PM Image 511 :Ceiling		Passage 17/03/2025 3:27 PM Image 512 :Ceiling

Inspector Signature



Date


21/03/25


Tenant



Date

27/03/25

	Passage 17/03/2025 3:28 PM Image 513 :Ceiling		Toilet 17/03/2025 3:28 PM Image 514 :Floor/ Tiles
	Toilet 17/03/2025 3:28 PM Image 515 :Floor/ Tiles		Toilet 17/03/2025 3:28 PM Image 516 :Floor/ Tiles




Toilet
17/03/2025 3:29 PM
Image 517 :Walls/ Tiles




Toilet
17/03/2025 3:29 PM
Image 518 :Walls/ Tiles



Toilet
17/03/2025 3:29 PM
Image 519 :Walls/ Tiles



Toilet
17/03/2025 3:29 PM
Image 520 :Walls/ Tiles



Toilet

17/03/2025 3:29 PM
Image 521 :Walls/ Tiles



Toilet

17/03/2025 3:29 PM
Image 522 :Walls/ Tiles



Toilet

17/03/2025 3:30 PM
Image 523 :Door/ Doorframe




Toilet

17/03/2025 3:30 PM
Image 524 :Door/ Doorframe

Inspector Signature  Date 21/03/25 Tenant 

Date 27/03/25

	Toilet 17/03/2025 3:30 PM Image 525 :Door/ Doorframe		Toilet 17/03/2025 3:30 PM Image 526 :Door/ Doorframe
	Toilet 17/03/2025 3:30 PM Image 527 :Door/ Doorframe		Toilet 17/03/2025 3:30 PM Image 528 :Door/ Doorframe



Toilet
17/03/2025 3:30 PM
Image 529 :Door/ Doorframe



Toilet
17/03/2025 3:31 PM
Image 530 :Powerpoints/ Fixtures



Toilet
17/03/2025 3:31 PM
Image 531 :Toilet/ Cistern/ Seat



Toilet
17/03/2025 3:31 PM
Image 532 :Toilet/ Cistern/ Seat



Toilet
17/03/2025 3:31 PM
Image 533 :Toilet/ Cistern/ Seat



Toilet
17/03/2025 3:31 PM
Image 534 :Toilet/ Cistern/ Seat



Toilet
17/03/2025 3:31 PM
Image 535 :Toilet/ Cistern/ Seat




Toilet
17/03/2025 3:31 PM
Image 536 :Toilet/ Cistern/ Seat

	Toilet 17/03/2025 3:31 PM Image 537 :Toilet/ Cistern/ Seat		Toilet 17/03/2025 3:31 PM Image 538 :Toilet Roll Holder
	Toilet 17/03/2025 3:32 PM Image 539 :Exhaust Fan/ Vent		Toilet 17/03/2025 3:32 PM Image 540 :Exhaust Fan/ Vent

	Toilet 17/03/2025 3:32 PM Image 541 :Exhaust Fan/ Vent		Toilet 17/03/2025 3:32 PM Image 542 :Exhaust Fan/ Vent
	Toilet 17/03/2025 3:32 PM Image 543 :Exhaust Fan/ Vent		Toilet 17/03/2025 3:32 PM Image 544 :Exhaust Fan/ Vent

	Bedroom 2 17/03/2025 3:34 PM Image 545 :Cupboard		Bedroom 2 17/03/2025 3:34 PM Image 546 :Cupboard
	Bedroom 2 17/03/2025 3:34 PM Image 547 :Cupboard		Bedroom 2 17/03/2025 3:35 PM Image 548 :Cupboard

	Bedroom 2 17/03/2025 3:35 PM Image 549 :Cupboard		Bedroom 2 17/03/2025 3:35 PM Image 550 :Cupboard
	Bedroom 2 17/03/2025 3:35 PM Image 551 :Cupboard		Bedroom 2 17/03/2025 3:35 PM Image 552 :Cupboard



Bedroom 2

17/03/2025 3:36 PM

Image 553 :Floor



Bedroom 2

17/03/2025 3:36 PM

Image 554 :Floor



Bedroom 2

17/03/2025 3:36 PM

Image 555 :Floor



Bedroom 2

17/03/2025 3:37 PM

Image 556 :Walls

	Bedroom 2 17/03/2025 3:37 PM Image 557 :Walls		Bedroom 2 17/03/2025 3:37 PM Image 558 :Walls
	Bedroom 2 17/03/2025 3:37 PM Image 559 :Walls		Bedroom 2 17/03/2025 3:37 PM Image 560 :Walls

Inspector Signature



Date

21/03/25

Tenant



Date

27/03/25

	Bedroom 2 17/03/2025 3:37 PM Image 561 :Walls		Bedroom 2 17/03/2025 3:37 PM Image 562 :Walls
	Bedroom 2 17/03/2025 3:37 PM Image 563 :Walls		Bedroom 2 17/03/2025 3:37 PM Image 564 :Walls

Inspector Signature



Date

21/03/25

Tenant



Date

27/03/25

	Bedroom 2 17/03/2025 3:38 PM Image 565 :Walls		Bedroom 2 17/03/2025 3:38 PM Image 566 :Walls
	Bedroom 2 17/03/2025 3:38 PM Image 567 :Walls		Bedroom 2 17/03/2025 3:38 PM Image 568 :Walls

Inspector Signature



Date

21/03/25

Tenant



Date

27/03/25

	Bedroom 2 17/03/2025 3:38 PM Image 569 :Walls		Bedroom 2 17/03/2025 3:38 PM Image 570 :Walls
	Bedroom 2 17/03/2025 3:38 PM Image 571 :Walls		Bedroom 2 17/03/2025 3:38 PM Image 572 :Walls

Inspector Signature



Date

21/03/25

Tenant



Date

27/03/25

	Bedroom 2 17/03/2025 3:38 PM Image 573 :Walls		Bedroom 2 17/03/2025 3:38 PM Image 574 :Walls
	Bedroom 2 17/03/2025 3:39 PM Image 575 :Walls		Bedroom 2 17/03/2025 3:39 PM Image 576 :Door/ Doorframe

Inspector Signature



Date

21/03/25

Tenant



Date

27/03/25

	Bedroom 2 17/03/2025 3:39 PM Image 577 :Door/ Doorframe		Bedroom 2 17/03/2025 3:39 PM Image 578 :Door/ Doorframe
	Bedroom 2 17/03/2025 3:39 PM Image 579 :Door/ Doorframe		Bedroom 2 17/03/2025 3:39 PM Image 580 :Door/ Doorframe

Inspector Signature



Date

21/03/25

Tenant



Date

27/03/25

	Bedroom 2 17/03/2025 3:40 PM Image 581 :Door/ Doorframe		Bedroom 2 17/03/2025 3:40 PM Image 582 :Door/ Doorframe
	Bedroom 2 17/03/2025 3:40 PM Image 583 :Door/ Doorframe		Bedroom 2 17/03/2025 3:40 PM Image 584 :Door/ Doorframe

Inspector Signature



Date

21/03/25

Tenant



Date

27/03/25



Bedroom 2
17/03/2025 3:40 PM
Image 585 :Powerpoints/ Fixtures



Bedroom 2
17/03/2025 3:40 PM
Image 586 :Powerpoints/ Fixtures



Bedroom 2
17/03/2025 3:40 PM
Image 587 :Powerpoints/ Fixtures



Bedroom 2
17/03/2025 3:40 PM
Image 588 :Powerpoints/ Fixtures

	Bedroom 2 17/03/2025 3:40 PM Image 589 :Powerpoints/ Fixtures		Bedroom 2 17/03/2025 3:40 PM Image 590 :Powerpoints/ Fixtures
	Bedroom 2 17/03/2025 3:41 PM Image 591 :Windows/ Screens/ Window Saf...		Bedroom 2 17/03/2025 3:41 PM Image 592 :Windows/ Screens/ Window Sa...

Inspector Signature



Date

21/03/25


Tenant




Date

27/03/25

	Bedroom 2 17/03/2025 3:41 PM Image 593 :Windows/ Screens/ Window Sa...		Bedroom 2 17/03/2025 3:42 PM Image 594 :Windows/ Screens/ Window Sa...
	Bedroom 2 17/03/2025 3:41 PM Image 595 :Blinds/ Curtains		Bedroom 2 17/03/2025 3:41 PM Image 596 :Blinds/ Curtains

	Bedroom 2 17/03/2025 3:41 PM Image 597 :Blinds/ Curtains		Bedroom 2 17/03/2025 3:41 PM Image 598 :Blinds/ Curtains
	Bedroom 2 17/03/2025 3:42 PM Image 599 :Lights/ Fixtures		Bedroom 2 17/03/2025 3:42 PM Image 600 :Ceiling

	Bedroom 2 17/03/2025 3:42 PM Image 601 :Ceiling		Bedroom 2 17/03/2025 3:42 PM Image 602 :Ceiling
	Bedroom 3 17/03/2025 3:43 PM Image 603 :Cupboard		Bedroom 3 17/03/2025 3:43 PM Image 604 :Cupboard

	Bedroom 3 17/03/2025 3:44 PM Image 605 :Cupboard		Bedroom 3 17/03/2025 3:44 PM Image 606 :Cupboard
	Bedroom 3 17/03/2025 3:44 PM Image 607 :Cupboard		Bedroom 3 17/03/2025 3:44 PM Image 608 :Cupboard

Inspector Signature



Date

21/03/25


Tenant



Date

27/03/25

	Bedroom 3 17/03/2025 3:44 PM Image 609 :Cupboard		Bedroom 3 17/03/2025 3:44 PM Image 610 :Cupboard
	Bedroom 3 17/03/2025 3:44 PM Image 611 :Cupboard		Bedroom 3 17/03/2025 3:45 PM Image 612 :Floor



Bedroom 3

17/03/2025 3:45 PM

Image 613 :Floor



Bedroom 3

17/03/2025 3:45 PM

Image 614 :Floor



Bedroom 3

17/03/2025 3:45 PM


Image 615 :Floor



Bedroom 3

17/03/2025 3:45 PM

Image 616 :Floor



Bedroom 3

17/03/2025 3:45 PM

Image 617 :Floor



Bedroom 3

17/03/2025 3:45 PM

Image 618 :Walls



Bedroom 3

17/03/2025 3:45 PM

Image 619 :Walls




Bedroom 3

17/03/2025 3:46 PM

Image 620 :Walls

Inspector Signature  Date 21/03/25 Tenant 

Date 27/03/25

	Bedroom 3 17/03/2025 3:46 PM Image 621 :Walls		Bedroom 3 17/03/2025 3:46 PM Image 622 :Walls
	Bedroom 3 17/03/2025 3:46 PM Image 623 :Walls		Bedroom 3 17/03/2025 3:47 PM Image 624 :Walls

Inspector Signature



Date



21/03/25

Tenant



Date

27/03/25

	Bedroom 3 17/03/2025 3:47 PM Image 625 :Walls		Bedroom 3 17/03/2025 3:47 PM Image 626 :Walls
	Bedroom 3 17/03/2025 3:47 PM Image 627 :Walls		Bedroom 3 17/03/2025 3:47 PM Image 628 :Walls

Inspector Signature



Date

21/03/25

Tenant



Date

27/03/25

	Bedroom 3 17/03/2025 3:47 PM Image 629 :Walls		Bedroom 3 17/03/2025 3:48 PM Image 630 :Walls
	Bedroom 3 17/03/2025 3:48 PM Image 631 :Walls		Bedroom 3 17/03/2025 3:48 PM Image 632 :Walls

Inspector Signature



Date

21/03/25

Tenant



Date

27/03/25

	Bedroom 3 17/03/2025 3:48 PM Image 633 :Walls		Bedroom 3 17/03/2025 3:48 PM Image 634 :Walls
	Bedroom 3 17/03/2025 3:48 PM Image 635 :Walls		Bedroom 3 17/03/2025 3:48 PM Image 636 :Walls

Inspector Signature



Date


21/03/25

Tenant



Date

27/03/25



Bedroom 3

17/03/2025 3:49 PM

[Image 637 :Walls](#)



Bedroom 3

17/03/2025 3:49 PM

[Image 638 :Walls](#)



Bedroom 3

17/03/2025 3:49 PM


[Image 639 :Walls](#)



Bedroom 3

17/03/2025 3:49 PM

[Image 640 :Walls](#)

	Bedroom 3 17/03/2025 3:49 PM Image 641 :Walls		Bedroom 3 17/03/2025 3:49 PM Image 642 :Walls
	Bedroom 3 17/03/2025 3:49 PM Image 643 :Walls		Bedroom 3 17/03/2025 3:49 PM Image 644 :Walls

Inspector Signature



Date

21/03/25

Tenant



Date

27/03/25

	Bedroom 3 17/03/2025 3:50 PM Image 645 :Walls		Bedroom 3 17/03/2025 3:50 PM Image 646 :Walls
	Bedroom 3 17/03/2025 3:50 PM Image 647 :Door/ Doorframe		Bedroom 3 17/03/2025 3:50 PM Image 648 :Door/ Doorframe

	Bedroom 3 17/03/2025 3:50 PM Image 649 :Door/ Doorframe		Bedroom 3 17/03/2025 3:50 PM Image 650 :Door/ Doorframe
	Bedroom 3 17/03/2025 3:50 PM Image 651 :Door/ Doorframe		Bedroom 3 17/03/2025 3:50 PM Image 652 :Door/ Doorframe

	Bedroom 3 17/03/2025 3:50 PM Image 653 :Door/ Doorframe		Bedroom 3 17/03/2025 3:50 PM Image 654 :Door/ Doorframe
	Bedroom 3 17/03/2025 3:50 PM Image 655 :Door/ Doorframe		Bedroom 3 17/03/2025 3:50 PM Image 656 :Door/ Doorframe

Inspector Signature



Date

21/03/25

Tenant



Date

27/03/25

	Bedroom 3 17/03/2025 3:50 PM Image 657 :Door/ Doorframe		Bedroom 3 17/03/2025 3:51 PM Image 658 :Door/ Doorframe
	Bedroom 3 17/03/2025 3:51 PM Image 659 :Door/ Doorframe		Bedroom 3 17/03/2025 3:51 PM Image 660 :Powerpoints/ Fixtures

Inspector Signature  Date 21/03/25 Tenant 

Date 27/03/25



Bedroom 3
17/03/2025 3:51 PM
Image 661 :Powerpoints/ Fixtures




Bedroom 3
17/03/2025 3:51 PM
Image 662 :Powerpoints/ Fixtures



Bedroom 3
17/03/2025 3:51 PM
Image 663 :Powerpoints/ Fixtures



Bedroom 3
17/03/2025 3:51 PM
Image 664 :Powerpoints/ Fixtures



Bedroom 3

17/03/2025 3:52 PM


Image 665 :Windows/ Screens/ Window Sa...



Bedroom 3

17/03/2025 3:52 PM

Image 666 :Windows/ Screens/ Window Sa...



Bedroom 3

17/03/2025 3:52 PM

Image 667 :Windows/ Screens/ Window Sa...



Bedroom 3

17/03/2025 3:52 PM

Image 668 :Windows/ Screens/ Window Sa...

	Bedroom 3 17/03/2025 3:51 PM Image 669 :Blinds/ Curtains		Bedroom 3 17/03/2025 3:52 PM Image 670 :Blinds/ Curtains
	Bedroom 3 17/03/2025 3:52 PM Image 671 :Blinds/ Curtains		Bedroom 3 17/03/2025 3:53 PM Image 672 :Lights/ Fixtures



Bedroom 3

17/03/2025 3:53 PM

Image 673 :Ceiling



Bedroom 3

17/03/2025 3:53 PM

Image 674 :Ceiling



Bedroom 4

17/03/2025 3:54 PM

Image 675 :Cupboard




Bedroom 4

17/03/2025 3:54 PM

Image 676 :Cupboard





Bedroom 4
17/03/2025 3:54 PM
Image 677 :Cupboard



Bedroom 4
17/03/2025 3:54 PM
Image 678 :Cupboard



Bedroom 4
17/03/2025 3:54 PM
Image 679 :Cupboard




Bedroom 4
17/03/2025 3:54 PM
Image 680 :Cupboard

	Bedroom 4 17/03/2025 3:54 PM Image 681 :Cupboard		Bedroom 4 17/03/2025 3:54 PM Image 682 :Cupboard
	Bedroom 4 17/03/2025 3:55 PM Image 683 :Cupboard		Bedroom 4 17/03/2025 3:55 PM Image 684 :Cupboard

	Bedroom 4 17/03/2025 3:55 PM Image 685 :Cupboard		Bedroom 4 17/03/2025 3:55 PM Image 686 :Floor
	Bedroom 4 17/03/2025 3:55 PM Image 687 :Floor		Bedroom 4 17/03/2025 3:56 PM Image 688 :Floor

	Bedroom 4 17/03/2025 3:56 PM Image 689 :Floor		Bedroom 4 17/03/2025 3:56 PM Image 690 :Floor
	Bedroom 4 17/03/2025 3:56 PM Image 691 :Walls		Bedroom 4 17/03/2025 3:56 PM Image 692 :Walls

	Bedroom 4 17/03/2025 3:56 PM Image 693 :Walls		Bedroom 4 17/03/2025 3:57 PM Image 694 :Walls
	Bedroom 4 17/03/2025 3:57 PM Image 695 :Walls		Bedroom 4 17/03/2025 3:57 PM Image 696 :Walls

Inspector Signature



Date

21/03/25

Tenant



Date

27/03/25

	Bedroom 4 17/03/2025 3:57 PM Image 697 :Walls		Bedroom 4 17/03/2025 3:57 PM Image 698 :Walls
	Bedroom 4 17/03/2025 3:58 PM Image 699 :Walls		Bedroom 4 17/03/2025 3:58 PM Image 700 :Walls

Inspector Signature



Date

21/03/25

Tenant



Date

27/03/25

	Bedroom 4 17/03/2025 3:58 PM Image 701 :Walls		Bedroom 4 17/03/2025 3:58 PM Image 702 :Walls
	Bedroom 4 17/03/2025 3:58 PM Image 703 :Walls		Bedroom 4 17/03/2025 3:58 PM Image 704 :Walls

Inspector Signature



Date


21/03/25

Tenant




Date

27/03/25




Bedroom 4
17/03/2025 3:58 PM
[Image 705 :Walls](#)



Bedroom 4
17/03/2025 3:58 PM
[Image 706 :Walls](#)





Bedroom 4
17/03/2025 3:58 PM
[Image 707 :Walls](#)



Bedroom 4
17/03/2025 3:58 PM
[Image 708 :Walls](#)

Inspector Signature  Date 21/03/25 Tenant 

Date 27/03/25

	Bedroom 4 17/03/2025 3:58 PM Image 709 :Walls		Bedroom 4 17/03/2025 3:59 PM Image 710 :Walls
	Bedroom 4 17/03/2025 3:59 PM Image 711 :Walls		Bedroom 4 17/03/2025 3:59 PM Image 712 :Walls

Inspector Signature



Date

21/03/25


Tenant



Date

27/03/25

	Bedroom 4 17/03/2025 3:59 PM Image 713 :Walls		Bedroom 4 17/03/2025 3:59 PM Image 714 :Door/ Doorframe
	Bedroom 4 17/03/2025 3:59 PM Image 715 :Door/ Doorframe		Bedroom 4 17/03/2025 3:59 PM Image 716 :Door/ Doorframe

	Bedroom 4 17/03/2025 3:59 PM Image 717 :Door/ Doorframe		Bedroom 4 17/03/2025 3:59 PM Image 718 :Door/ Doorframe
	Bedroom 4 17/03/2025 4:00 PM Image 719 :Door/ Doorframe		Bedroom 4 17/03/2025 4:00 PM Image 720 :Door/ Doorframe

	Bedroom 4 17/03/2025 4:00 PM Image 721 :Door/ Doorframe		Bedroom 4 17/03/2025 4:00 PM Image 722 :Door/ Doorframe
	Bedroom 4 17/03/2025 4:00 PM Image 723 :Door/ Doorframe		Bedroom 4 17/03/2025 4:00 PM Image 724 :Door/ Doorframe



Bedroom 4
17/03/2025 4:00 PM
Image 725 :Powerpoints/ Fixtures



Bedroom 4
17/03/2025 4:00 PM
Image 726 :Powerpoints/ Fixtures



Bedroom 4
17/03/2025 4:00 PM
Image 727 :Powerpoints/ Fixtures



Bedroom 4
17/03/2025 4:00 PM
Image 728 :Powerpoints/ Fixtures



Bedroom 4

17/03/2025 4:00 PM
Image 729 :Powerpoints/ Fixtures



Bedroom 4

17/03/2025 4:01 PM
Image 730 :Powerpoints/ Fixtures




Bedroom 4

17/03/2025 4:01 PM
Image 731 :Windows/ Screens/ Window Saf...



Bedroom 4


17/03/2025 4:01 PM
Image 732 :Windows/ Screens/ Window Sa...



Bedroom 4
17/03/2025 4:02 PM
Image 733 :Windows/ Screens/ Window Sa...



Bedroom 4
17/03/2025 4:02 PM
Image 734 :Windows/ Screens/ Window Sa...



Bedroom 4
17/03/2025 4:02 PM
Image 735 :Windows/ Screens/ Window Sa...



Bedroom 4
17/03/2025 4:02 PM
Image 736 :Windows/ Screens/ Window Sa...

	Bedroom 4 17/03/2025 4:01 PM Image 737 :Blinds/ Curtains		Bedroom 4 17/03/2025 4:01 PM Image 738 :Blinds/ Curtains
	Bedroom 4 17/03/2025 4:01 PM Image 739 :Blinds/ Curtains		Bedroom 4 17/03/2025 4:01 PM Image 740 :Blinds/ Curtains



Bedroom 4

17/03/2025 4:01 PM
Image 741 :Blinds/ Curtains



Bedroom 4

17/03/2025 4:03 PM
Image 742 :Lights/ Fixtures



Bedroom 4

17/03/2025 4:03 PM
Image 743 :Ceiling



Bedroom 4

17/03/2025 4:03 PM
Image 744 :Ceiling

Inspector Signature  Date 21/03/25 Tenant 

Date 27/03/25



Bathroom

17/03/2025 4:04 PM

Image 745 :Ceiling



Bathroom

17/03/2025 4:04 PM

Image 746 :Ceiling



Bathroom

17/03/2025 4:04 PM


Image 747 :Floor/ Tiles



Bathroom

17/03/2025 4:04 PM

Image 748 :Floor/ Tiles



Bathroom
17/03/2025 4:04 PM
Image 749 :Floor/ Tiles



Bathroom
17/03/2025 4:04 PM
Image 750 :Floor/ Tiles




Bathroom
17/03/2025 4:05 PM
Image 751 :Walls/ Tiles



Bathroom
17/03/2025 4:05 PM
Image 752 :Walls/ Tiles

	Bathroom 17/03/2025 4:05 PM Image 753 :Walls/ Tiles		Bathroom 17/03/2025 4:05 PM Image 754 :Walls/ Tiles
	Bathroom 17/03/2025 4:05 PM Image 755 :Walls/ Tiles		Bathroom 17/03/2025 4:05 PM Image 756 :Walls/ Tiles

	Bathroom 17/03/2025 4:05 PM Image 757 :Walls/ Tiles		Bathroom 17/03/2025 4:05 PM Image 758 :Walls/ Tiles
	Bathroom 17/03/2025 4:05 PM Image 759 :Walls/ Tiles		Bathroom 17/03/2025 4:05 PM Image 760 :Walls/ Tiles

Inspector Signature



Date


21/03/25

Tenant



Date

27/03/25




Bathroom

17/03/2025 4:06 PM
Image 761 :Walls/ Tiles



Bathroom

17/03/2025 4:06 PM
Image 762 :Walls/ Tiles



Bathroom

17/03/2025 4:06 PM
Image 763 :Walls/ Tiles




Bathroom

17/03/2025 4:06 PM
Image 764 :Door/ Doorframe

Inspector Signature  Date 21/03/25 Tenant 

Date 27/03/25



Bathroom
17/03/2025 4:06 PM
Image 765 :Door/ Doorframe



Bathroom
17/03/2025 4:06 PM
Image 766 :Door/ Doorframe



Bathroom
17/03/2025 4:06 PM
Image 767 :Door/ Doorframe



Bathroom
17/03/2025 4:06 PM
Image 768 :Door/ Doorframe

Inspector Signature  Date 21/03/25 Tenant 

Date 27/03/25

	Bathroom 17/03/2025 4:06 PM Image 769 :Door/ Doorframe		Bathroom 17/03/2025 4:07 PM Image 770 :Door/ Doorframe
	Bathroom 17/03/2025 4:07 PM Image 771 :Door/ Doorframe		Bathroom 17/03/2025 4:07 PM Image 772 :Door/ Doorframe



Bathroom
17/03/2025 4:07 PM
Image 773 :Door/ Doorframe



Bathroom
17/03/2025 4:07 PM
Image 774 :Powerpoints/ Fixtures



Bathroom
17/03/2025 4:12 PM
Image 775 :Powerpoints/ Fixtures



Bathroom
17/03/2025 4:07 PM
Image 776 :Mirror/ Cabinet



Bathroom

17/03/2025 4:07 PM
Image 777 :Taps/ Basin



Bathroom

17/03/2025 4:07 PM
Image 778 :Taps/ Basin



Bathroom

17/03/2025 4:07 PM
Image 779 :Taps/ Basin



Bathroom

17/03/2025 4:07 PM
Image 780 :Taps/ Basin

Inspector Signature  Date 21/03/25 Tenant 

Date 27/03/25



Bathroom
17/03/2025 4:08 PM
Image 781 :Cupboard/ Drawers



Bathroom
17/03/2025 4:08 PM
Image 782 :Cupboard/ Drawers



Bathroom
17/03/2025 4:08 PM
Image 783 :Cupboard/ Drawers




Bathroom
17/03/2025 4:08 PM
Image 784 :Cupboard/ Drawers



Bathroom
17/03/2025 4:08 PM
Image 785 :Cupboard/ Drawers



Bathroom
17/03/2025 4:08 PM
Image 786 :Cupboard/ Drawers



Bathroom
17/03/2025 4:08 PM
Image 787 :Cupboard/ Drawers



Bathroom
17/03/2025 4:08 PM
Image 788 :Cupboard/ Drawers



Bathroom
17/03/2025 4:08 PM
Image 789 :Cupboard/ Drawers



Bathroom
17/03/2025 4:08 PM
Image 790 :Cupboard/ Drawers



Bathroom
17/03/2025 4:08 PM
Image 791 :Cupboard/ Drawers



Bathroom
17/03/2025 4:09 PM
Image 792 :Cupboard/ Drawers



Bathroom
17/03/2025 4:09 PM
Image 793 :Cupboard/ Drawers




Bathroom
17/03/2025 4:09 PM
Image 794 :Cupboard/ Drawers



Bathroom
17/03/2025 4:09 PM
Image 795 :Cupboard/ Drawers



Bathroom
17/03/2025 4:09 PM
Image 796 :Bath



Bathroom

17/03/2025 4:09 PM

Image 797 :Bath



Bathroom

17/03/2025 4:09 PM

Image 798 :Bath



Bathroom

17/03/2025 4:09 PM

Image 799 :Bath




Bathroom

17/03/2025 4:09 PM

Image 800 :Bath

	Bathroom 17/03/2025 4:09 PM Image 801 :Bath		Bathroom 17/03/2025 4:09 PM Image 802 :Bath
	Bathroom 17/03/2025 4:09 PM Image 803 :Bath		Bathroom 17/03/2025 4:09 PM Image 804 :Bath



Bathroom

17/03/2025 4:09 PM

Image 805 :Bath



Bathroom

17/03/2025 4:10 PM

Image 806 :Shower/ Screen/ Taps



Bathroom

17/03/2025 4:10 PM


Image 807 :Shower/ Screen/ Taps



Bathroom

17/03/2025 4:10 PM


Image 808 :Shower/ Screen/ Taps



Bathroom
17/03/2025 4:10 PM
Image 809 :Shower/ Screen/ Taps




Bathroom
17/03/2025 4:10 PM
Image 810 :Shower/ Screen/ Taps



Bathroom
17/03/2025 4:10 PM
Image 811 :Shower/ Screen/ Taps



Bathroom
17/03/2025 4:10 PM
Image 812 :Shower/ Screen/ Taps



Bathroom

17/03/2025 4:10 PM

Image 813 :Shower/ Screen/ Taps



Bathroom

17/03/2025 4:10 PM

Image 814 :Shower/ Screen/ Taps



Bathroom

17/03/2025 4:10 PM


Image 815 :Shower/ Screen/ Taps



Bathroom

17/03/2025 4:10 PM

Image 816 :Shower/ Screen/ Taps



Bathroom
17/03/2025 4:11 PM
Image 817 :Shower/ Screen/ Taps



Bathroom
17/03/2025 4:11 PM
Image 818 :Shower/ Screen/ Taps



Bathroom
17/03/2025 4:11 PM
Image 819 :Shower/ Screen/ Taps




Bathroom
17/03/2025 4:11 PM
Image 820 :Towel Rails



Bathroom
17/03/2025 4:12 PM
Image 821 :Windows/ Screens/ Window Saf...




Bathroom
17/03/2025 4:12 PM
Image 822 :Windows/ Screens/ Window Sa...



Bathroom
17/03/2025 4:12 PM
Image 823 :Windows/ Screens/ Window Sa...



Bathroom
17/03/2025 4:12 PM
Image 824 :Windows/ Screens/ Window Sa...



Bathroom
17/03/2025 4:11 PM
Image 825 :Blinds/ Curtains




Bathroom
17/03/2025 4:11 PM
Image 826 :Blinds/ Curtains



Bathroom
17/03/2025 4:11 PM
Image 827 :Blinds/ Curtains



Bathroom
17/03/2025 4:11 PM
Image 828 :Blinds/ Curtains



Bathroom

17/03/2025 4:12 PM

Image 829 :Lights/ Fixtures



Bathroom

17/03/2025 4:12 PM

Image 830 :Exhaust Fan/ Vents



Laundry

17/03/2025 4:27 PM


Image 831 :Cupboards



Laundry

17/03/2025 4:27 PM

Image 832 :Cupboards



Laundry
17/03/2025 4:27 PM
Image 833 :Cupboards



Laundry
17/03/2025 4:27 PM
Image 834 :Cupboards



Laundry
17/03/2025 4:27 PM
Image 835 :Cupboards



Laundry
17/03/2025 4:27 PM
Image 836 :Cupboards

	Laundry 17/03/2025 4:27 PM Image 837 :Cupboards		Laundry 17/03/2025 4:27 PM Image 838 :Cupboards
	Laundry 17/03/2025 4:27 PM Image 839 :Cupboards		Laundry 17/03/2025 4:28 PM Image 840 :Cupboards



Laundry
17/03/2025 4:28 PM
Image 841 :Cupboards



Laundry
17/03/2025 4:28 PM
Image 842 :Cupboards



Laundry
17/03/2025 4:28 PM
Image 843 :Cupboards



Laundry
17/03/2025 4:28 PM
Image 844 :Cupboards



Laundry
17/03/2025 4:28 PM
Image 845 :Cupboards




Laundry
17/03/2025 4:28 PM
Image 846 :Cupboards



Laundry
17/03/2025 4:28 PM
Image 847 :Cupboards



Laundry
17/03/2025 4:28 PM
Image 848 :Cupboards



Laundry
17/03/2025 4:28 PM
Image 849 :Cupboards



Laundry
17/03/2025 4:28 PM
Image 850 :Cupboards



Laundry
17/03/2025 4:23 PM
Image 851 :Floor/ Tiles



Laundry
17/03/2025 4:23 PM
Image 852 :Floor/ Tiles

	Laundry 17/03/2025 4:23 PM Image 853 :Floor/ Tiles		Laundry 17/03/2025 4:24 PM Image 854 :Walls/ Tiles
	Laundry 17/03/2025 4:24 PM Image 855 :Walls/ Tiles		Laundry 17/03/2025 4:24 PM Image 856 :Walls/ Tiles

Inspector Signature



Date

21/03/25

Tenant



Date

27/03/25

	Laundry 17/03/2025 4:24 PM Image 857 :Walls/ Tiles		Laundry 17/03/2025 4:24 PM Image 858 :Walls/ Tiles
	Laundry 17/03/2025 4:24 PM Image 859 :Walls/ Tiles		Laundry 17/03/2025 4:24 PM Image 860 :Walls/ Tiles

Inspector Signature



Date

21/03/25


Tenant



Date

27/03/25

	Laundry 17/03/2025 4:25 PM Image 861 :Walls/ Tiles		Laundry 17/03/2025 4:25 PM Image 862 :Walls/ Tiles
	Laundry 17/03/2025 4:25 PM Image 863 :Walls/ Tiles		Laundry 17/03/2025 4:25 PM Image 864 :Walls/ Tiles



Laundry
17/03/2025 4:25 PM
Image 865 :Walls/ Tiles



Laundry
17/03/2025 4:25 PM
Image 866 :Walls/ Tiles




Laundry
17/03/2025 4:25 PM
Image 867 :Walls/ Tiles




Laundry
17/03/2025 4:25 PM
Image 868 :Walls/ Tiles

Inspector Signature  Date 21/03/25 Tenant 

Date 27/03/25



Laundry
17/03/2025 4:25 PM
Image 869 :Walls/ Tiles




Laundry
17/03/2025 4:29 PM
Image 870 :Washing Machine/ Taps



Laundry
17/03/2025 4:27 PM
Image 871 :Washing Tub



Laundry
17/03/2025 4:27 PM
Image 872 :Washing Tub



Laundry
17/03/2025 4:27 PM
Image 873 :Washing Tub



Laundry
17/03/2025 4:27 PM
Image 874 :Washing Tub



Laundry
17/03/2025 4:27 PM
Image 875 :Washing Tub



Laundry
17/03/2025 4:26 PM
Image 876 :Door/ Doorframe

	Laundry 17/03/2025 4:26 PM Image 877 :Door/ Doorframe		Laundry 17/03/2025 4:26 PM Image 878 :Door/ Doorframe
	Laundry 17/03/2025 4:26 PM Image 879 :Door/ Doorframe		Laundry 17/03/2025 4:26 PM Image 880 :Door/ Doorframe

Inspector Signature



Date

21/03/25


Tenant



Date

27/03/25

	Laundry 17/03/2025 4:26 PM Image 881 :Door/ Doorframe		Laundry 17/03/2025 4:26 PM Image 882 :Door/ Doorframe
	Laundry 17/03/2025 4:26 PM Image 883 :Door/ Doorframe		Laundry 17/03/2025 4:26 PM Image 884 :Door/ Doorframe

	Laundry 17/03/2025 4:26 PM Image 885 :Door/ Doorframe		Laundry 17/03/2025 4:26 PM Image 886 :Door/ Doorframe
	Laundry 17/03/2025 4:26 PM Image 887 :Door/ Doorframe		Laundry 17/03/2025 4:26 PM Image 888 :Door/ Doorframe

Inspector Signature



Date

21/03/25


Tenant



Date

27/03/25

	Laundry 17/03/2025 4:26 PM Image 889 :Door/ Doorframe		Laundry 17/03/2025 4:30 PM Image 890 :Door/ Doorframe
	Laundry 17/03/2025 4:30 PM Image 891 :Door/ Doorframe		Laundry 17/03/2025 4:30 PM Image 892 :Door/ Doorframe



Laundry
17/03/2025 4:30 PM
Image 893 :Door/ Doorframe



Laundry
17/03/2025 4:30 PM
Image 894 :Door/ Doorframe




Laundry
17/03/2025 4:30 PM
Image 895 :Door/ Doorframe



Laundry
17/03/2025 4:31 PM
Image 896 :Door/ Doorframe

Inspector Signature  Date 21/03/25 Tenant 

Date 27/03/25



Laundry
17/03/2025 4:31 PM
Image 897 :Door/ Doorframe




Laundry
17/03/2025 4:31 PM
Image 898 :Door/ Doorframe



Laundry
17/03/2025 4:29 PM
Image 899 :Powerpoints/ Fixtures



Laundry
17/03/2025 4:29 PM
Image 900 :Blinds/ Curtains



Laundry
17/03/2025 4:29 PM
Image 901 :Blinds/ Curtains




Laundry
17/03/2025 4:29 PM
Image 902 :Blinds/ Curtains



Laundry
17/03/2025 4:29 PM
Image 903 :Blinds/ Curtains




Laundry
17/03/2025 4:30 PM
Image 904 :Blinds/ Curtains




Laundry
17/03/2025 4:30 PM
Image 905 :Blinds/ Curtains



Laundry
17/03/2025 4:30 PM
Image 906 :Blinds/ Curtains



Laundry
17/03/2025 4:30 PM
Image 907 :Blinds/ Curtains



Laundry
17/03/2025 4:31 PM
Image 908 :Lights/ Fixtures



Laundry
17/03/2025 4:31 PM
Image 909 :Lights/ Fixtures



Laundry
17/03/2025 4:31 PM
Image 910 :Ceiling



Laundry
17/03/2025 4:31 PM
Image 911 :Ceiling




Exterior
17/03/2025 4:37 PM
Image 912 :Letterbox



Exterior
17/03/2025 4:37 PM
Image 913 :Letterbox




Exterior
17/03/2025 4:37 PM
Image 914 :Letterbox




Exterior
17/03/2025 4:16 PM
Image 915 :Gate/ Fence




Exterior
17/03/2025 4:16 PM
Image 916 :Gate/ Fence




Exterior
17/03/2025 4:16 PM
Image 917 :Gate/ Fence




Exterior
17/03/2025 4:16 PM
Image 918 :Gate/ Fence



Exterior
17/03/2025 4:17 PM
Image 919 :Gate/ Fence




Exterior
17/03/2025 4:17 PM
Image 920 :Gate/ Fence




Exterior
17/03/2025 4:17 PM
Image 921 :Gate/ Fence




Exterior
17/03/2025 4:19 PM
Image 922 :Gate/ Fence



Exterior
17/03/2025 4:19 PM
Image 923 :Gate/ Fence



Exterior
17/03/2025 4:21 PM
Image 924 :Gate/ Fence



Exterior
17/03/2025 4:21 PM
Image 925 :Gate/ Fence



Exterior
17/03/2025 4:21 PM
Image 926 :Gate/ Fence




Exterior
17/03/2025 4:21 PM
Image 927 :Gate/ Fence



Exterior
17/03/2025 4:34 PM
Image 928 :Gate/ Fence

Inspector Signature  Date 21/03/25 Tenant 

Date 27/03/25



Exterior
17/03/2025 4:35 PM
Image 929 :Gate/ Fence




Exterior
17/03/2025 4:35 PM
Image 930 :Gate/ Fence



Exterior
17/03/2025 4:19 PM
Image 931 :Driveway



Exterior
17/03/2025 4:19 PM
Image 932 :Driveway




Exterior
17/03/2025 4:19 PM
Image 933 :Driveway




Exterior
17/03/2025 4:19 PM
Image 934 :Driveway



Exterior
17/03/2025 4:19 PM
Image 935 :Driveway



Exterior
17/03/2025 4:20 PM
Image 936 :Driveway



Exterior
17/03/2025 4:20 PM
Image 937 :Driveway



Exterior
17/03/2025 4:21 PM
Image 938 :Driveway




Exterior
17/03/2025 4:21 PM
Image 939 :Driveway




Exterior
17/03/2025 4:16 PM
Image 940 :Footpaths

Inspector Signature  Date 21/03/25 Tenant 


Date 27/03/25



Exterior
17/03/2025 4:17 PM
Image 941 :Footpaths



Exterior
17/03/2025 4:17 PM
Image 942 :Footpaths




Exterior
17/03/2025 4:17 PM
Image 943 :Footpaths



Exterior
17/03/2025 4:34 PM
Image 944 :Footpaths

Inspector Signature  Date 21/03/25 Tenant 

Date 27/03/25



Exterior
17/03/2025 4:34 PM
Image 945 :Footpaths




Exterior
17/03/2025 4:34 PM
Image 946 :Footpaths



Exterior
17/03/2025 4:35 PM
Image 947 :Footpaths




Exterior
17/03/2025 4:35 PM
Image 948 :Footpaths



Exterior
17/03/2025 4:35 PM
Image 949 :Footpaths




Exterior
17/03/2025 4:35 PM
Image 950 :Footpaths



Exterior
17/03/2025 4:36 PM
Image 951 :Front Lawn




Exterior
17/03/2025 4:36 PM
Image 952 :Front Lawn



Exterior
17/03/2025 4:16 PM
Image 953 :Back Lawn



Exterior
17/03/2025 4:16 PM
Image 954 :Back Lawn



Exterior
17/03/2025 4:16 PM
Image 955 :Back Lawn



Exterior
17/03/2025 4:15 PM
Image 956 :Garden Lights



Exterior
17/03/2025 4:15 PM
Image 957 :Garden Lights



Exterior
17/03/2025 4:21 PM
Image 958 :Garden Lights



Exterior
17/03/2025 4:21 PM
Image 959 :Garden Lights



Exterior
17/03/2025 4:34 PM
Image 960 :Garden Lights



Exterior
17/03/2025 4:35 PM
Image 961 :Garden Lights



Exterior
17/03/2025 4:35 PM
Image 962 :Garden Lights



Exterior
17/03/2025 4:35 PM
Image 963 :Garden Lights



Exterior
17/03/2025 4:15 PM
Image 964 :External Awnings



Exterior
17/03/2025 4:15 PM
Image 965 :External Awnings



Exterior
17/03/2025 4:15 PM
Image 966 :External Awnings



Exterior
17/03/2025 4:15 PM
Image 967 :External Awnings



Exterior
17/03/2025 4:15 PM
Image 968 :External Awnings



Exterior
17/03/2025 4:15 PM
Image 969 :External Awnings



Exterior
17/03/2025 4:15 PM
Image 970 :External Awnings



Exterior
17/03/2025 4:15 PM
Image 971 :External Awnings



Exterior
17/03/2025 4:33 PM
Image 972 :Front Porch/ Verandah



Exterior

17/03/2025 4:34 PM


Image 973 :Front Porch/ Verandah



Exterior

17/03/2025 4:34 PM

Image 974 :Front Porch/ Verandah



Exterior

17/03/2025 4:34 PM


Image 975 :Front Porch/ Verandah



Exterior

17/03/2025 4:21 PM

Image 976 :Hosing/ Taps



Exterior
17/03/2025 4:35 PM
Image 977 :Hosing/ Taps



Exterior
17/03/2025 4:16 PM
Image 978 :Garden Beds




Exterior
17/03/2025 4:16 PM
Image 979 :Garden Beds



Exterior
17/03/2025 4:16 PM
Image 980 :Garden Beds

Inspector Signature  Date 21/03/25 Tenant 

Date 27/03/25




Exterior
17/03/2025 4:21 PM
Image 981 :Garden Beds



Exterior
17/03/2025 4:36 PM
Image 982 :Garden Beds




Exterior
17/03/2025 4:36 PM
Image 983 :Garden Beds



Exterior
17/03/2025 4:36 PM
Image 984 :Garden Beds

Inspector Signature  Date 21/03/25 Tenant 

Date 27/03/25



Exterior
17/03/2025 4:36 PM
Image 985 :Garden Beds



Exterior
17/03/2025 4:37 PM
Image 986 :Garden Beds



Exterior
17/03/2025 4:37 PM
Image 987 :Garden Beds



Storeroom
17/03/2025 4:18 PM
Image 988 :Floor



Storeroom

17/03/2025 4:18 PM


Image 989 :Walls



Storeroom

17/03/2025 4:18 PM

Image 990 :Walls



Storeroom

17/03/2025 4:18 PM


Image 991 :Walls



Storeroom

17/03/2025 4:17 PM


Image 992 :Door/ Doorframe



Storeroom
17/03/2025 4:17 PM
Image 993 :Door/ Doorframe




Storeroom
17/03/2025 4:18 PM
Image 994 :Door/ Doorframe



Storeroom
17/03/2025 4:18 PM
Image 995 :Powerpoints/ Fixtures



Storeroom
17/03/2025 4:18 PM
Image 996 :Powerpoints/ Fixtures



Storeroom

17/03/2025 4:18 PM

Image 997 :Powerpoints/ Fixtures



Storeroom

17/03/2025 4:18 PM

Image 998 :Lights/ Fixtures



Storeroom

17/03/2025 4:18 PM


Image 999 :Ceiling




Entrance

Image 1000 :Floor

T

	Entrance Image 1001 :Floor T		Entrance Image 1002 :Floor T
	Entrance Image 1003 :Walls T		Entrance Image 1004 :Walls T

	Entrance Image 1005 :Walls T		Entrance Image 1006 :Door/ Doorframe T
	Entrance Image 1007 :Door/ Doorframe T		Entrance Image 1008 :Door/ Doorframe T

	Entrance Image 1009 :Door/ Doorframe T		Lounge Room Image 1010 :Floor T
	Lounge Room Image 1011 :Floor T		Lounge Room Image 1012 :Floor T

Inspector Signature



Date

21/03/25

Tenant



Date

27/03/25

	Lounge Room Image 1013 :Floor T		Lounge Room Image 1014 :Floor T
	Lounge Room Image 1015 :Floor T		Lounge Room Image 1016 :Floor T

Inspector Signature



Date


21/03/25

Tenant



Date

27/03/25

	Lounge Room Image 1017 :Floor T		Lounge Room Image 1018 :Walls T
	Lounge Room Image 1019 :Walls T		Lounge Room Image 1020 :Walls T

Inspector Signature



Date


21/03/25

Tenant



Date

27/03/25




Lounge Room
Image 1021 :Walls

T



Lounge Room
Image 1022 :Door/ Doorframe

T



Lounge Room
Image 1023 :Door/ Doorframe

T




Lounge Room
Image 1024 :Blinds/ Curtains

T

Inspector Signature  Date 21/03/25 Tenant 


Date 27/03/25



Lounge Room
Image 1025 :Blinds/ Curtains T



Lounge Room
Image 1026 :Blinds/ Curtains T



Bedroom
Image 1027 :Walk In Robe T



Bedroom
Image 1028 :Walk In Robe T

	Bedroom Image 1029 :Walk In Robe T		Bedroom Image 1030 :Walk In Robe T
	Bedroom Image 1031 :Walk In Robe T		Bedroom Image 1032 :Floor T

Inspector Signature



Date

21/03/25


Tenant



Date

27/03/25

	Bedroom Image 1033 :Floor T		Bedroom Image 1034 :Floor T
	Bedroom Image 1035 :Floor T		Bedroom Image 1036 :Floor T

	Bedroom Image 1037 :Walls T		Bedroom Image 1038 :Walls T
	Bedroom Image 1039 :Walls T		Bedroom Image 1040 :Walls T

Inspector Signature



Date


21/03/25

Tenant



Date

27/03/25

	Bedroom Image 1041 :Walls T		Bedroom Image 1042 :Walls T
	Bedroom Image 1043 :Walls T		Bedroom Image 1044 :Walls T

Inspector Signature



Date


21/03/25

Tenant



Date

27/03/25



Bedroom

Image 1045 :Door/ Doorframe



Bedroom

Image 1046 :Door/ Doorframe



Bedroom


Image 1047 :Door/ Doorframe




Bedroom

Image 1048 :Blinds/ Curtains







Bedroom
Image 1049 :Blinds/ Curtains T




Bedroom
Image 1050 :Blinds/ Curtains T



Ensuite
Image 1051 :Floor/ Tiles T



Ensuite
Image 1052 :Door/ Doorframe T



Ensuite

Image 1053 :Mirror/ Cabinet



Ensuite

Image 1054 :Taps/ Basin



Ensuite

Image 1055 :Taps/ Basin



Ensuite

Image 1056 :Taps/ Basin





Ensuite

Image 1057 :Taps/ Basin

T



Ensuite

Image 1058 :Taps/ Basin

T



Ensuite

Image 1059 :Cupboard/ Drawers

T



Ensuite

Image 1060 :Cupboard/ Drawers

T

Inspector Signature

Date

21/03/25

Tenant

Date


27/03/25



Ensuite
Image 1061 :Cupboard/ Drawers T




Ensuite
Image 1062 :Cupboard/ Drawers T



Ensuite
Image 1063 :Shower/ Screen/ Taps T



Ensuite
Image 1064 :Shower/ Screen/ Taps T



Ensuite
Image 1065 :Shower/ Screen/ Taps T



Ensuite
Image 1066 :Shower/ Screen/ Taps T




Ensuite
Image 1067 :Shower/ Screen/ Taps T



Ensuite
Image 1068 :Shower/ Screen/ Taps T


	Ensuite Image 1069 :Shower/ Screen/ Taps T		Ensuite Image 1070 :Walls/ Tiles T
	Ensuite Image 1071 :Walls/ Tiles T		Ensuite Image 1072 :Toilet/ Cistern/ Seat T



Ensuite
Image 1073 :Windows/ Screens/ Window S T




Kitchen
Image 1074 :Floor/ Tiles T



Kitchen
Image 1075 :Floor/ Tiles T



Kitchen
Image 1076 :Floor/ Tiles T




Kitchen
Image 1077 :Floor/ Tiles

T



Kitchen
Image 1078 :Floor/ Tiles

T



Kitchen
Image 1079 :Walls/ Tiles

T



Kitchen
Image 1080 :Walls/ Tiles

T

Inspector Signature  Date 21/03/25 Tenant 

Date 27/03/25

	Kitchen Image 1081 :Walls/ Tiles T		Kitchen Image 1082 :Walls/ Tiles T
	Kitchen Image 1083 :Walls/ Tiles T		Kitchen Image 1084 :Cupboards T

	Kitchen Image 1085 :Cupboards T		Kitchen Image 1086 :Benchtops/ Tiling T
	Kitchen Image 1087 :Benchtops/ Tiling T		Kitchen Image 1088 :Benchtops/ Tiling T

Inspector Signature



Date

21/03/25

Tenant



Date

27/03/25

	Kitchen Image 1089 :Benchtops/ Tiling T		Kitchen Image 1090 :Dishwasher T
	Kitchen Image 1091 :Oven T		Kitchen Image 1092 :Oven T



Kitchen

Image 1093 :Blinds/ Curtains

T



Kitchen

Image 1094 :Blinds/ Curtains

T



Family room

Image 1095 :Walls

T




Family room

Image 1096 :Walls

T

	Family room Image 1097 :Powerpoints/ Fixtures T		Family room Image 1098 :Walls T
	Family room Image 1099 :Door/ Doorframe T		Family room Image 1100 :Door/ Doorframe T



Family room
Image 1101 :Door/ Doorframe T



Family room
Image 1102 :Blinds/ Curtains T



Family room
Image 1103 :Blinds/ Curtains T



Laundry
Image 1104 :Walls/ Tiles T

Inspector Signature  Date 21/03/25 Tenant 

Date 27/03/25

	Laundry Image 1105 :Walls/ Tiles T		Laundry Image 1106 :Door/ Doorframe T
	Laundry Image 1107 :Blinds/ Curtains T		Passage Image 1108 :Walls T

	Passage Image 1109 :Walls T		Passage Image 1110 :Walls T
	Passage Image 1111 :Walls T		Passage Image 1112 :Walls T

Inspector Signature



Date


21/03/25

Tenant



Date

27/03/25

	Passage Image 1113 :Walls T		Passage Image 1114 :Door/ Doorframe T
	Passage Image 1115 :Ceiling T		Passage Image 1116 :Walls T

Inspector Signature



Date

21/03/25


Tenant




Date

27/03/25

	Toilet Image 1117 :Walls/ Tiles T		Toilet Image 1118 :Walls/ Tiles T
	Toilet Image 1119 :Toilet/ Cistern/ Seat T		Toilet Image 1120 :Toilet/ Cistern/ Seat T

	Bedroom 2 Image 1121 :Cupboard T		Bedroom 2 Image 1122 :Door/ Doorframe T
	Bedroom 2 Image 1123 :Door/ Doorframe T		Bedroom 2 Image 1124 :Walls T

	Bedroom 2 Image 1125 :Ceiling T		Bedroom 3 Image 1126 :Walls T
	Bedroom 3 Image 1127 :Door/ Doorframe T		Bedroom 3 Image 1128 :Door/ Doorframe T

	Bedroom 4 Image 1129 :Cupboard T		Bedroom 4 Image 1130 :Walls T
	Bedroom 4 Image 1131 :Walls T		Bedroom 4 Image 1132 :Walls T

Inspector Signature



Date

21/03/25

Tenant



Date

27/03/25

	Bedroom 4 Image 1133 :Door/ Doorframe T		Bedroom 4 Image 1134 :Lights/ Fixtures T
	Bathroom Image 1135 :Walls/ Tiles T		Bathroom Image 1136 :Walls/ Tiles T



Bathroom

Image 1137 :Walls/ Tiles



Bathroom

Image 1138 :Door/ Doorframe



Bathroom

Image 1139 :Door/ Doorframe





Bathroom

Image 1140 :Taps/ Basin



	Bathroom Image 1141 :Taps/ Basin T		Bathroom Image 1142 :Cupboard/ Drawers T
	Bathroom Image 1143 :Cupboard/ Drawers T		Bathroom Image 1144 :Cupboard/ Drawers T


	Bathroom Image 1145 :Bath T		Bathroom Image 1146 :Bath T
	Bathroom Image 1147 :Bath T		Bathroom Image 1148 :Bath T



Bathroom
Image 1149 :Shower/ Screen/ Taps T




Bathroom
Image 1150 :Shower/ Screen/ Taps T



Bathroom
Image 1151 :Blinds/ Curtains T



Exterior
Image 1152 :Driveway T




Exterior

Image 1153 :Gate/ Fence



Exterior

Image 1154 :Gate/ Fence



Exterior

Image 1155 :Gate/ Fence



Exterior

Image 1156 :Footpaths



Inspector Signature


Date

21/03/25

Tenant

Date

27/03/25




Exterior
Image 1157 :Back Lawn

T



Exterior
Image 1158 :Back Lawn

T




Exterior
Image 1159 :Back Lawn

T



Exterior
Image 1160 :Back Lawn


T



Exterior
Image 1161 :Back Lawn



Exterior
Image 1162 :Back Lawn




Exterior
Image 1163 :Back Lawn



Exterior
Image 1164 :Back Lawn






Exterior
Image 1165 :Back Lawn



Storeroom
Image 1166 :Floor




Storeroom
Image 1167 :Floor



Exterior
Image 1168 :External Awnings





Exterior
Image 1169 :External Awnings T



Exterior
Image 1170 :External Awnings T



Exterior
Image 1171 :External Awnings T




Lounge Room
Image 1172 :Door/ Doorframe T

Inspector Signature  Date 21/03/25 Tenant 

Date 27/03/25

	Lounge Room Image 1173 :Door/ Doorframe T		Exterior Image 1174 :Front Lawn T
	Exterior Image 1175 :Front Lawn T		Exterior Image 1176 :Back Lawn T




Exterior
Image 1177 :Back Lawn

T



Exterior
Image 1178 :Garden Beds

T




Exterior
Image 1179 :Garden Beds

T



Exterior
Image 1180 :Garden Beds

T



Exterior
Image 1181 :Garden Beds

T



Exterior
Image 1182 :Garden Beds

T



Exterior
Image 1183 :Garden Beds

T




Exterior
Image 1184 :Garden Beds

T

Inspector Signature  Date 21/03/25 Tenant 


Date 27/03/25



Exterior
Image 1185 :Garden Beds



Exterior
Image 1186 :Garden Beds



Exterior
Image 1187 :Garden Beds



Exterior
Image 1188 :Garden Beds



Confirmation of acceptance of condition report

I acknowledge and accept that the above report, including my comments and photographs, reflects the condition of the property as at the time I signed the report.

Signed on behalf of landlord

Emma Elliott - Davies



21/3/2025 at 07:41

Tenant Acceptance

Tenant 1: Housing Authority



Signing device: Safari
Date: 27/3/2025 at 04:50

Audit Trail

	Report sent to tenants
21/3/2025 at 07:41	Sent from IP address: 10.0.1.70
	Report opened by The Housing Author...
25/3/2025 at 06:38	Opened from Chrome IP address: 203.5.201.60
	Report opened by The Housing Author...
25/3/2025 at 06:38	Opened from Chrome IP address: 20.28.9.245
	Report opened by The Housing Author...
25/3/2025 at 06:39	Opened from Chrome IP address: 203.5.201.60
	Report opened by The Housing Author...
25/3/2025 at 06:41	Opened from Chrome IP address: 203.5.201.60
	Report opened by The Housing Author...
25/3/2025 at 06:44	Opened from Chrome IP address: 203.5.201.60
	Report opened by The Housing Author...
25/3/2025 at 06:45	Opened from Chrome IP address: 203.5.201.60
	Report opened by The Housing Author...
25/3/2025 at 06:45	Opened from Chrome IP address: 203.5.201.60

Audit Trail

	Report opened by The Housing Author...
25/3/2025	Opened from Chrome at 06:46 IP address: 203.5.201.60
	Report opened by The Housing Author...
25/3/2025	Opened from Chrome at 06:50 IP address: 203.5.201.60
	Report opened by The Housing Author...
25/3/2025	Opened from Chrome at 08:31 IP address: 203.5.201.60
	Report opened by The Housing Author...
25/3/2025	Opened from Chrome at 08:32 IP address: 20.53.239.89
	Report opened by The Housing Author...
26/3/2025	Opened from Chrome at 03:06 IP address: 203.5.201.60
	Report opened by The Housing Author...
26/3/2025	Opened from Chrome at 03:06 IP address: 20.11.232.32
	Report opened by The Housing Author...
27/3/2025	Opened from Safari at 01:11 IP address: 1.146.164.78
	Report opened by The Housing Author...
27/3/2025	Opened from Chrome at 01:12 IP address: 104.210.79.75
	Report opened by The Housing Author...
27/3/2025	Opened from Chrome at 02:55 IP address: 203.5.201.60

Inspector Signature  Date 21/03/25 Tenant 

Date 27/03/25

Audit Trail



Report opened by The Housing Author...

27/3/2025 Opened from Chrome
at 02:55 IP address: 20.28.53.228



Report signed by Housing Authority

27/3/2025 Signed from Safari
at 04:50 IP address: 1.146.157.86

Inspector Signature  Date 21/03/25 Tenant 

Date 27/03/25